



भारत कोकिंग कोल लिमिटेड  
(एक मिनिस्टर कम्पनी)  
(कोल इण्डिया लिमिटेड का एक अंग)  
महाप्रबन्धक का कार्यालय  
कुसुन्डा क्षेत्र, पो: कुसुन्डा, धनबाद, झारखण्ड

Ref No. BCCL/KA-6/Env./2017/ 52

Date : 24.05.2017

To,  
The Director(s)  
Ministry of Environment, Forest and Climate Change (MoEFCC),  
(Govt. of India)  
Regional Office (ECZ),  
Bungalow No. A-2,  
Shyamali Colony,  
Ranchi - 834002

**Sub : Six monthly compliance report on Environmental Clearance Conditions for the period from October '2016 to March '2017 in respect of Cluster-VI Group of mines, EC order no.: J-11015/183/2011-1A.II(M), dated 26-08-2013**

Dear Sir,

Enclosed please find herewith six monthly compliance report on environmental clearance conditions for the period from **October '2016 to March '2017** in respect of **Cluster-VI** Group of mines, EC order no.: J-11015/183/2011-1A.II(M), dated 26-08-2013 for your kind perusal.

With regards,

**Encl.:** as above with soft copy (CD)

  
Addl. General Manager/SO (Min.)  
**Kusunda Area, BCCL**

**Copy:**

- (1) Director, 1A Monitoring Cell,  
Paryavaran Bhawan,  
CGO Complex, New Delhi- 110003
- (2) The Member Secretary,  
Jharkhand State Pollution Control Board,  
TA Division Building, HEC, Dhurwa, Ranchi-834004
- (3) General Manager, Kusunda Area.
- (4) Dy.GM(Environment), BCCL, Koyla Bhawan, Dhanbad
- (5) Office copy

## **COMPLIANCE OF EC CONDITIONS of CLUSTER-VI**

**EC order no.: J-11015/183/2011-1A.II(M), dated 26-08-2013**

**(October '16 to March '17)**

| <b>Sl. no.</b> | <b>A. Specific Conditions by MOEF:</b>  | <b>Compliance</b>  |
|----------------|---|--|
| i              | The maximum production from the two opencast section in the cluster shall not exceed beyond that for which environmental clearance has been granted.  | The approved peak production capacity for East Bassuria OC and Gondudih Khas Kusunda OC under Kusunda Area are total 4.55 MTPA and for whole cluster consisting of East Bassuria Colliery, Bassuria Colliery, Gondudih Khas Kusunda Colliery and Godhur Colliery, 7.631 MTPA. <b>Total production of all mines of the cluster-VI in 2016-'17 is 2.676 MT which is well within the limit.</b>   |
| ii             | The two nallahs passing through the mines should be preserved and made functional to drain the water.   | Complied. In every year, before monsoon the nallahs are made clear of any obstacles to ensure proper draining of water.  |
| iii            | The coal transport to the siding will continue by road to the siding within 2 km with payloader loading into Rly. Wagons for a period of 5 years by which time the proposed silo in Rly. Siding not being affected in the Jharia Action Plan will be constructed for RLS loading into railway wagons. | Coal transport to siding is being done by road to siding with payloader loading into railway wagons.   |
| iv             | As subsidence is on higher side in Godhur colliery, special attention should be given for control and monitoring of subsidence.   | For control and monitoring of threat of subsidence at fire affected area within Godhur lease hold special attention has been made by mine management. JRDA has completed survey the basties at fire affected area for evacuation & rehabilitation of the inhabitants under Jharia Master Plan and partially distributed Identity Cards (about 350 nos.), but evacuation of non-BCCL persons have not yet been done by JRDA. Colliery Management have allotted quarters at other safe place to employees residing at/near fire affected area for their early evacuation and accordingly shifting of employees is going on at the allotted quarters at newly constructed colonies at East Bassuriya, Karmik Nagar and Jagjivan Nagar. Besides, Safety Committee team is functioning there at the Colliery for inspection/supervision-followed by meeting regularly (ie. at every month and whenever required) at Godhur Colliery for early detection of any pot hole, fume and report to mine management for early action. Pot holes detected near Muchi Basti |



|      |  |   |
|------|--|---|
|      |  | have been filled up by incombustible materials (sand & quarry OB). Fiery coal is being dugged out by OC method to control fire as well as environmental pollution.  |
| v    | All old dumps will be filled back in mine voids. At the end of mining there should not be any OBD and should be only one void which shall not exceed 30 m deep.  | It shall be complied. Action is being taken as specified in EMP.  |
| vi   | An increase in the CSR   | BCCL is taking up activities from the HQ level and through its administrative areas for the implementation of CSR activities. For this purpose a CSR cell is functioning which is headed by General Manger(CSR) under the direct control of Director(Personnel) of the company. A details of CSR activities at Kusunda Area is given in the CSR Booklet.  |
| vii  | Dhanbad Action Plan, as CEPI, be implanted where ever is applicable.   | Dhanbad Action Plan has been prepared in consultation with Jharkhand State Pollution Control Board for entire BCCL and not clusterwise. It is being implemented comprehensively for all the mines of BCCL including mines of Kusunda Area. Some of the salient actions of this cluster are enclosed as Annexure-D.  |
| viii | Since the cluster is situated close to Dhanbad, thick green belt and residential areas should be done along the periphery of ML area. Avenue-plantation should be done along the roads which are used for coal transport and measures to arrest coal dust while transporting by covering the trucks and water sprinkling measures etc. | It is being complied. Plantation at decoaled OB dump area is already being executed for development of green belts as directed in EC. Adequate water sprinkling is being done at coal transportation road regularly by mobile water sprinklers, and coal transportation is being done by covering trucks by tarpaulin as measures to control dust pollution. At degraded OB dumps at Gondudih eco-restoration work are in successful progress.<br>Details of plantation done and programme of eco-restoration are enclosed as Annexure-B. |
| ix   | Whereas laudable efforts have been made in drawing skill development programmes along with Planning Commission of Gol , all out efforts should be made to ensure that they are suitably employed either with the PP or elsewhere.  | Training programmes for all employees are conducted regularly at mine Vocational Training Centre as per Mine VT Rule and also through NSDC (National Skill Development Corporation), and special training are being conducted at mine VT Centre, at HRD Deptt. of BCCL HQ and outside of Company for development of their skill. The required details are given in Annexure-E.  |
| x    | The measure to identify in the Environmental Plan for Cluster- VI groups of mine and the conditions  | Master Plan activities are dovetailed with compliance of environmental clearance conditions.  |

|    |  |   |
|----|--|---|
|    | <p>given in this environmental clearance letter shall be dovetailed to the implementation of the Jharia Action Plan.</p>   | <p>The master plan deals with fire control and rehabilitation activities of fire affected areas in the leasehold of BCCL.</p> <p>By implementing complete digging out of fiery seams with water spraying in force as fire control measures air pollution and emission of Green House Gases (GHGs) from the fire affected areas are being prevented. Further rehabilitation of the families from the fire endangered area to the safe places is being taken-up with the help of State Govt. of Jharkhand. The Master plan is being implemented for BCCL as per the prioritization of fire and rehabilitation activities in approved Master Plan. The brief status of Rehabilitation and Fire control measures are enclosed in Booklet of CSR, R&amp;R and Transportation</p>   |
| xi | <p>The proponent shall prepare time -series maps of the Jharia Coalfields through NRSA to monitor and prevent fire problems in the Jharia Coalfields by Isothermal mapping /imaging and monitoring temperatures of the coal seams (whether they are close to spontaneous ignition temperatures) and based on which, areas with potential fire problems shall be identified. Measures to prevent ingress of air (Ventilation) in such areas, to prevent restart fresh/spread fires in other areas including in mines of cluster VI shall be undertaken. Expertise available internationally could also be utilized for control of fire in Jharia Coalfields and for their reclamation and to further minimize time for fire and subsidence control. Isothermal mapping using thermal imaging has been got done by NRSA. Measures would be taken to prevent ingress of air (ventilation) in such areas, which may re-start fresh fires</p> | <p>NRSC had conducted survey of fires of Jharia coalfield by remote sensing methods using thermal infra-red data and land subsidence mapping of Jharia coalfield using Inter-ferometric SAR data. Total fire affected area in Jharia Coalfield has been reduced. Report of NRSC has been attached herewith. Further, the work has been awarded and the next survey by NRSC will be started soon.</p> <p>For control and monitoring of threat of subsidence at fire affected area within Godhur lease hold special attention has been made by mine management. JRDA has nearly completed survey the basties at fire affected area for evacuation &amp; rehabilitation of the inhabitants under Jharia Master Plan and partially distributed Identity Cards, evacuation of non-BCCL persons are being done by JRDA. Colliery Management have allotted quarters at other safe place to employees residing at/near fire affected area for their early evacuation and accordingly shifting of employees is going on at the allotted quarters at newly constructed colonies at East Bassuriya , Jagjivan Nagar and Karmik Nagar. Besides, one special team headed by senior mine official has been made at Colliery for inspection/supervision of the lease hold area of Godhur for early detection of any pot hole, fume and report to mine management for early action. Under Jharia Master Plan, fire patch of V/VI/VII/VIII seam at Gareria Section of East</p> |

3

by



|      |  |  |
|------|--|--|
|      |  | Bassuriya, Kusunda Area about 1,70,000 m <sup>3</sup> have been filled by mitti/incombustible OB, rest void will be filled up by quarry OB of East Bassuriya OC.   |
| xii  | Underground mining should be taken up after completion of reclamation of Opencast mine area.   | It shall be complied.  |
| xiii | The OB material should be crushed like sand and be used for stowing in underground mines.  | At present no underground mining work is going on in the mines of Kusunda Area.  |
| xiv  | A detailed calendar plan of production with plan for OB dumping and backfilling (for OC mines) and reclamation and final mine closure plan for each mine of cluster-VI shall be drawn up and implemented. The schedule of backfilling should be clearly brought out and submit the same to MoEF.   | Production & OB back filling plan is enclosed as annexure –A 1, 2.<br>Mine closure plan as per the guidelines of Ministry of Coal has been prepared by Regional Institute –II , Central Mine planning and Design Institute (CMPDI), Dhanbad. The financial provisions required for the implementation of mine closure plan are being kept in accounts, and accordingly action are being taken. |
| xv   | The embankment constructed along the river boundary shall be of suitable dimensions and critical patches shall be strengthened by stone pitching on the river front side and stabilized with plantation so as to withstand the peak water flow and prevent mine inundation   | It is being followed. Embankments have been constructed and maintained as specified in EC (Figure 1).  |
| xvi  | No mining shall be undertaken where underground fires continue. Measure shall be taken to prevent/check such fire including in old OB dump areas where the fire could start due to presence of coal/shale with sufficient carbon content.  | Fiery coal seams are being dug out completely by OC method. Action is being taken to control, mine fires as specified in Jharia Master Plan and the mining is being done as per the guidelines and permissions of Directorate General of Mines Safety (DGMS).  |
| xvii | There shall be no internal OB dumps. There will be 8 external OB Dumps covering an area of 32.84 Ha. The height of the dumps shall be 16 m and the total quantity shall be of 5.247 Mm <sup>3</sup> . The final mine voids will have an area of 66.76 ha (Filled up with water). with depth of 25 m bgl. The entire mined out area shall be re-vegetated. Areas where opencast mining was carried out and completed shall be reclaimed immediately thereafter. It was observed that most of the OB are reclaimed total area 441.24 ha at the end of mining where reclaimed external OB dump 32.84 ha and internal OB Dump 120.34 ha. Green Belt over an area of 66.12 ha. Density of tree plantation 2500 trees/ ha of plants which of and | It is being complied. Backfilling of OB is going on concurrent with mining and at the end of mining activity the area will be re-vegetated and reclaimed as per EMP. Plantation work have already been done with the help of DFO, Dhanbad. At degraded OB dump areas eco-restoration work is in successful progress.<br>(Annexure-B)   |

|           |  |   |
|-----------|--|---|
|           | abandoned. The proponent should dump all the OB material in abandoned mines.   |   |
| xvii<br>i | Mining shall be carried out as per statuette from the streams/nalas flowing within the lease and maintaining a safe distance from the nalas flowing along the lease boundary. A safety barrier of a minimum 60m width shall be maintained along the nalas/water bodies. The small water bodies in OC shall be protected to the extent feasible and the embankment proposed along water body shall be strengthened with stone pitching. | It is being followed. Embankments have been constructed and maintained as specified in EC   |
| xix       | Active OB dumps near water bodies and rivers should be rehandled for backfilling abandoned mine voids. However, those which have been biologically reclaimed need not be disturbed.  | No OB is being dumped near any water bodies.  |
| xx        | Thick green belt shall be developed along undisturbed areas, mine boundary and in mine reclamation.  | It is being complied. Plantation/eco-restoration work is going on at degraded OB dump area successfully. For green belt development plantation /eco-restoration program is enclosed in Annexure-B.  |
| xxi       | Specific mitigative measures identified for the Jharia Coalfields in the Environmental Action Plan prepared for Dhanbad as a critically polluted area and relevant for Cluster VI shall be implemented.  | Dhanbad Action Plan has been prepared in consultation with Jharkhand Pollution Control Board for entire BCCL and not clusterwise. It is being implemented comprehensively for all the mines of BCCL. Some of the salient actions of this cluster are enclosed in Annexure-D.  |
| xxii      | The locations of monitoring stations in the Jharia Coalfields should be finalized in consultation with the Jharkhand State Pollution Control Board.  | The locations of monitoring stations has been finalized in consultation with JSPCB and the Environmental monitoring of mines/units of BCCL as per the requirement of environmental Acts, Laws, Environmental Clearance conditions, etc . The work is now being carried out by CMPDI. Environment Monitoring Report provided by CMPDI is attached as Annexure- C   |
| xxii<br>i | The Committee stated that smoke/dust emission vary from source to source (fuel wood, coal ,fly ash from TPPs, silica from natural dust, etc) and a Source Apportionment Study should be got carried out for the entire Jharia Coalfields. Mineralogical composition study should be undertaken on the composition of the suspended particulate matter (PM10 and PM2.5) in Jharia Coalfields and also quantified. These studies         | Tender for conducting source apportionment study for BCCL was floated twice, however, none of the bidders qualified. Therefore, as per the MoU "Sustainable Coal Mining in Coal India Limited" entered between CIL and NEERI, NEERI Nagpur was approached for conducting Source Apportionment Study BCCL for compliance of EC conditions. The proposal regarding Conducting the Source Apportionment Study has been submitted by NEERI. Presently it has been submitted to CIL for further scrutiny and approval. |



|       |   |  |
|-------|---|--|
|       | would help ascertain source and extent of the air pollution, based on which appropriate mitigative measures could be taken.   |  |
| xxiv  | The Plan for conveyor-cum—rail for Cluster-VI should be dovetailed with Jharia Action Plan. The Committee desired that road transportation of coal during Phase—I should be by mechanically covered trucks, which should be introduced at the earliest. Coal dispatch shall be diverted from the present rail sidings to Rapid Loading System (RLS) soon after the construction and commissioning of the RLS at Maheshpur is completed. The railway siding order issued and same would come in 3 years. The details of same should be provided to ministry. The mode of transportation of coal by truck till Railway Siding should be by mechanically covered trucks. | CMPDIL, RI-II has been requested to conduct study and prepare the plan in this regard.<br>By that time transportation is being done by covering vehicle with tarpaulin cover and loading wagons by payloaders at sidings.  |
| xxv   | 1387 no. of PAF's should be rehabilitated at cost of Rs 10,768.17 Lakhs as per the approved Jharia Action Plan.   | It is being complied.  |
| xxvi  | Regular monitoring of subsidence movement on the surface over and around the working area and impact on natural drainage pattern, water bodies, vegetation, structure, roads, and surroundings shall be continued till movement ceases completely. In case of observation of any high rate of subsidence movement, appropriate effective corrective measures shall be taken to avoid loss of life and material. Cracks shall be effectively plugged with ballast and clayey soil/suitable material.   | No underground mining work is going on in this Area. For control and monitoring of threat of subsidence at fire affected area within Godhur lease hold special attention has been made by mine management. JRDA has completed survey the basties at fire affected area for evacuation & rehabilitation of the inhabitants under Jharia Master Plan and partially distributed Identity Cards, evacuation of non-BCCL persons are being done by JRDA. Colliery Management have allotted quarters at other safe place to employees residing at/near fire affected area for their early evacuation and accordingly shifting of employees is going on at the allotted quarters at newly constructed colonies at East Bassuriya, Karmik Nagar and Jagjivan Nagar. Besides, one special team headed by senior mine official has been made at Colliery for inspection/supervision of the lease hold area of Godhur for early detection of any pot hole, fume and report to mine management for early action. |
| xxvii | Sufficient coal pillars shall be left un extracted around the air shaft (within the subsidence influence area) to protect from any damage from subsidence, if any.  | Complied. Action is being taken as specified in EMP.   |

|            |  |   |
|------------|--|---|
| xxvi<br>ii | High root density tree species shall be selected and planted over areas likely to be affected by subsidence.   | It will be complied, if required  |
| xxix       | Depression due to subsidence resulting in water accumulating within the low lying areas shall be filled up or drained out by cutting drains.   | It will be complied, if required  |
| xxx        | Solid barriers shall be left below the roads falling within the blocks to avoid any damage to the roads.   | It has been complied and maintained   |
| xxxi       | No depillaring operation shall be carried out below the township/colony.   | No underground mining operation is going on in Kusunda Area   |
| xxxi<br>i  | A detailed CSR Action Plan shall be prepared for Cluster VI group of mines. As stated by the Proponent, it is formulating a detailed Corporate Social Responsibility (CSR) Action Plan through Tata Institute of Social Sciences (TISS), Mumbai which will consist of need-based base-line survey, CSR Action Plan, CSR Auditing and monitoring mechanism etc. Director (Per.), BCCL. along with a team visited TISS/ National CSR Hub, Mumbai on 18th Jun, 2012 for finalizing the MoU with TISS and National CSR Hub for conducting base-line survey, empanelment of NGOs and formulating the project specific CSR action plan for BCCL. The Action Plan for Corporate Social Responsibility will include 5% of the retained earnings of the previous year subject to minimum of Rs. 5 per tonne of coal production of the previous year will be provided for Corporate Social Responsibility (CSR), an amount of Rs. 381.55 lakhs/year has been year marked for the CSR activities. | CSR activities have been taken up on priority basis. The details of activities is shown in the Booklet of CSR, R&R and Transportation . |
| xxxi<br>ii | The area within Cluster VI ML existing as waste land and not being acquired shall be put for productive use under CSR and developed with fruit bearing and other useful species for the local communities. A third party evaluation shall be got carried out regularly for the proper implementation of activities undertaken in the project area under CSR. Issue raised in the Public Hearing shall also be integrated with activities being taken up under CSR. The details of CSR undertaken along with budgetary provisions for the village-wise various activities and expenditures there on shall be uploaded on the  | CSR activities have been taken up on priority basis.. The details of activities are enclosed .  |



|             |   |  |
|-------------|---|--|
|             | company website every year. The company must give priority to capacity building both within the company and to the local youth, who are motivated to carry out the work in future. The gap/space available between the entire mine area should be suitably planted with native species. Plantation should also be made in vacant area and along the road side so as to reduce dust pollution. | Plantation at degraded OB backfilled area and office/colonies premises has been done for development of green belts as per EC. Eco-restoration work are in successful progress at degraded at OB dump areas.<br><br>Details of plantation to be done and programme of eco-restoration are enclosed in Annexure- B.   |
| xxx<br>v    | The mine water should be treated properly before supply to the villager.  | Mine water is treated by water filter plant before supply to colonies. For which in Kusunda Area, four Pressure Filters, one Slow Sand Filter and two Rapid Gravity Filter Plant are running and at East Bassuriya newly constructed Colony, installation of two Pressure Filters are under process.   |
| xxx<br>v    | Details of transportation, CSR, R&R. and implementation of environmental action plan for each of the clusters-VI should be brought out in a booklet form within a year and regularly updated.   | being complied.  |
| xxx<br>vi   | Central recreation park with herbal garden should be developed for use of all inhabitants.  | It shall be complied.  |
| xxx<br>vii  | Mine discharge water shall be treated to meet standards prescribed standards before discharge into natural water courses/agriculture. The quality of the water discharged shall be monitored at the outlet points and proper records maintained thereof and uploaded regularly on the company website.  | Being complied. The work of monitoring of ambient air and water is being carried out by CMPDI.   |
| xxx<br>viii | No groundwater shall be used for the mining activities. Additional water required, if any shall be met from mine water or by recycling/reuse of the water from the existing activities and from rainwater harvesting measures. The project authorities shall meet water requirement of nearby village(s) in case the village wells go dry to dewatering of mine.                              | No ground water is being utilized for the purpose of industrial use. Mine water has been channelized through pipelines and through delivery in to the old quarry for its community use & industrial use. Drinking water is being purchased from the Mineral Area Development Authority (MADA). Further for the utilization of mine water following actions has been taken by the company<br><b>Installation of filter plants:</b> Mine water is treated by water filter plant before supply to colonies. For which in Kusunda Area, four Pressure Filters, one Slow Sand Filter and two Rapid Gravity Filter Plant are running and at East Bassuriya newly constructed Colony, installation of two Pressure Filters are under process.<br><b>Rain water Harvesting:</b> Rain water is accumulated at |

dy

by

|            |  |   |
|------------|--|---|
|            |  | dip most portion of OC mines and at abandoned UG galleries at discontinued UG mines/patch through garland drains for ground water recharge.   |
| xxx<br>ix. | The void shall be converted into a water reservoir of a maximum depth of 15-20 m and shall be gently sloped and the upper benches of the reservoir shall be stabilized with plantation and the periphery of the reservoir fenced. The abandoned pits and voids should be backfilled with OB and reclaimed with plantation and or may be used for pisciculture.   | It shall be complied.   |
| xi         | Regular monitoring of groundwater level and quality of the study area shall be carried out by establishing a network of existing wells and construction of new piezometers. The monitoring for quantity shall be done four times a year in pre-monsoon(May), monsoon(August), post-monsoon(November) and winter(January) seasons and for quality including Arsenic and Fluoride during the month of May. Data thus collected shall be submitted to the Ministry of Environment & Forest and to the Central Pollution Control Board/SPCB quarterly within one month of monitoring. Rainwater harvesting measures shall be undertaken in case monitoring of water table indicates a declining trend. | Regular monitoring of Ground water is being carried out by CMPDI. Proposal for establishment of new piezometers is under process.   |
| xli        | ETP shall also be provided for workshop, and CHP, if any. Effluents shall be treated to conform to prescribe standards in case discharge into the natural water course.  | It shall be complied.   |
| xlii       | For monitoring land use pattern and for post mining land use, a time series of land use maps, based on satellite imagery (on a scale of 1:5000) of the core zone and buffer zone, from the start of the project until end of mine life shall be prepared once in 3 years(for any one particular season which is consistent in the time series), and the report submitted to MOEF and its Regional office at Bhubaneswar.   | Presently a time series map of vegetation cover in the Jharia Coal Field is being carried out through CMPDI Ranchi using satellite imagery for every 3 years. CMPDI has started to prepare "Time series of land use maps based on satellite imagery of the core zone and buffer zone. |
| xliii      | A Final Mine Closure Plan along with details of Corpus Fund shall be submitted to the Ministry of Environment & Forests five year before mine closure for approval. Habitat Restoration Plan of the mine area shall be carried out using a mix of  | CMPDI has prepared Mine Closure Plan for progressive mine closure activities which are being implemented at mines. Final Mine Closure Plan will be prepared in time.  |



|      |   |  |
|------|---|--|
|      | native species found in the original eco system which were conserved in-situ and ex-situ in an identified area within the lease for reintroduction in the mine during mine reclamation and at the post mining stage for habitat restoration, the mining plan and post-mining plan, closure plan should be prepared and submitted to the Ministry; |  |
| xliv | A separate management structure for implementing environment policy and socio-economic issues and the capacity building required in this regard.  | <p>A full-fledged Environment Department, headed by a HoD (Environment) along with a suitable qualified multidisciplinary team of executives has been established in Headquarters. They are also trained in ecological restoration, sustainable development, rainwater harvesting methods etc. At the Area level, one Executive in area has also been nominated as Nodal Officer (Environment) under General Manager of Area to co-ordinate environmental issues to the Project Officer of mine and one officer at each mine level, under Project Officer is looking after the environment related jobs and also entrusted with the responsibility of compliance and observance of the environmental Acts/ Laws including environment protection measures .The activities are monitored on regular basis at Area and at Head quarters levels. GM (Environment) at head quarter level, co-ordinates with all the Areas and reports to the Director (Technical) and in turn he reports to the CMD of the company.</p> <p>The team is multidisciplinary and very much motivative under the guidance of company's Director (Technical) and CMD. Further capacity building at both corporate and operating level is being done.</p> |
| Xlv  | Corporate Environment Responsibility.   |  |
| (a.) | The Company shall have a well laid down Environment Policy approved by the Board of Directors.  | A well defined Corporate Environment Policy has already been laid down and approved by the Board of Directors. This is also posted on BCCL website.  |
| (b.) | The Environment Policy shall prescribe for standard operating process/procedures to bring into focus any infringements/deviation/violation of the environmental or forest norms/conditions.   | Complied.  |
| (c.) | The hierarchical system or Administrative Order of the company to deal with environmental issues and for ensuring compliance with the   | A hierarchical system of the company to deal with environmental issues from corporate level to mine level already exists.  |

|      |   |   |
|------|---|---|
|      | environmental clearance conditions shall be furnished.  |   |
| (d.) | To have proper checks and balances, the company shall have a well laid down system of reporting of non-compliances/violations of environmental norms to the Board of Directors of the company and/or shareholders or stakeholders at large.   | Being complied.   |
| B.   | <u>General Conditions</u>   |   |
| i    | No change in mining technology and scope of working shall be made without 'prior approval of the Ministry of Environment and Forests.   | Being followed.   |
| ii   | No change in the calendar plan of production for quantum of mineral coal shall be made.   | Being followed. Production of clusters are well within the production capacity as per EC.   |
| iii  | Four ambient air quality monitoring stations shall be established in the core zone as well as in the buffer zone for PM10, PM2.5, SO2 and NOx monitoring. Location of the stations shall be decided based on the meteorological data, topographical features and environmentally and ecologically sensitive targets in consultation with the State Pollution Control Board. Monitoring of heavy metals such as Hg, As, Ni, Cd, Cr ,etc. carried out at least once in six months.                | Air quality monitoring stations and monitoring of ambient environment has been established after consultation with State Pollution Control Board. CMPDIL is presently doing the monitoring work .Results of monitoring is enclosed as Annexure-C. |
| iv   | Data on ambient air quality (PM10, PM 2.5, SO2 and NOX) and heavy metals such as Hg, As Ni, Cd, Cr and other monitoring data shall be regularly submitted to the Ministry including its Regional Office at Bhubaneswar and to the State Pollution Control Board and the Central Pollution Control Board once in six months. Random verification of samples through analysis from independent laboratories recognized under the EPA rules, 1986 shall be furnished as part of compliance report. | It is being complied.   |
| v    | Adequate measures shall be taken for control of noise levels below 85 dBA in the work environment. Workers engaged in blasting and drilling operations, operation of HEMM, etc shall be provided with ear plugs/muffs.  | Being complied  |





|      |   |  |
|------|---|--|
| vi   | Industrial wastewater (workshop and waste water from the mine) shall be properly collected, treated so as to conform to the standards prescribed under GSR 422 (E) dated 19th May 1993 and 31st December 1993 or as amended from time to time before discharge. Oil and grease trap shall be installed before discharge of workshop effluents.  | It is being followed .Mine water is being reutilized for industrial purposes (sprinkling, cooling/ fire control etc.)  |
| vii  | Vehicular emissions shall be kept under control and regularly monitored. Vehicles used for transporting the mineral shall be covered with tarpaulins and optimally loaded.  | It is being complied.  |
| viii | Monitoring of environmental quality parameters shall be carried out through establishment of adequate number and type of pollution monitoring and analysis equipment in consultation with the State Pollution Control Board and data got analyzed through a laboratory recognized under EPA Rules, 1986.  | Air quality monitoring stations and monitoring of ambient environment has been established after consultation with and approval from State Pollution Control Board. The monitoring work is being carried out by CMPDIL.  |
| ix   | Personnel working in dusty areas shall wear protective respiratory devices and they shall also be provided with adequate training and information on safety and health aspects.   | Being Complied. A separate full fledged Human Resource Development Deptt. is conducting regular training programme on these issues. Apart from this Vocational Training Centers are existing in the Area which provides periodical training on the safety and occupational health issue to each of the workers working in the mines. Training status is enclosed as annexure-E |
| x    | Occupational health surveillance programme of the workers shall be undertaken periodically to observe any contractions due to exposure to dust and to take corrective measures, if needed an records maintained thereof. The quality of environment due to outsourcing and he health and safety issues of the outsourced manpower should be addressed by the company white outsourcing. | Initial Medical Examination (IME) and Periodical Medical Examination (PME) of all the personnel of the Area is carried out at Bhuli PME Centre, Bhuli, Dhanbad as per the Statutes and guidelines of Director General of Mines Safety (DGMS). Data enclosed as Annexure-E  |
| xi   | A separate environmental management cell with suitable qualified personnel shall be set up under the control of a Senior Executive, who will report directly to the Head of the company.  | A full-fledged Environment Department, headed by a HoD (Environment) along with a suitable qualified multidisciplinary team of executives has been established in Headquarters. They are also trained in ecological restoration, sustainable development,  |

|      |  |  |
|------|--|--|
|      |  | <p>rainwater harvesting methods etc. At the Area level, one Executive in area has also been nominated as Nodal Officer (Environment) under General Manager of Area to co-ordinate environmental issues to the Project Officer of mine and one officer at each mine level, under Project Officer is looking after the environment related jobs and also entrusted with the responsibility of compliance and observance of the environmental Acts/ Laws including environment protection measures .The activities are monitored on regular basis at Area and at Head quarters levels. GM (Environment) at head quarter level, co-ordinates with all the Areas and reports to the Director (Technical) and in turn he reports to the CMD of the company.</p> <p>The team is multidisciplinary and very much motivative under the guidance of company's Director (Technical) and CMD. Further capacity building at both corporate and operating level is being done.</p> |
| xii  | The funds earmarked for environmental protection measures shall be kept in separate account and shall not be diverted for other purpose. Year-wise expenditure shall be reported to this Ministry and its Regional Office at Bhubaneswar   | Being complied   |
| xiii | The Project authorities shall advertise at least in two local newspapers widely circulated around the project, one of which shall be in the vernacular language of the locality concerned within seven days of the clearance letter informing that the project has been accorded environmental clearance and a copy of the clearance letter is available with the State Pollution control Board and may also be seen at the website of the ministry of Environment & Forests at <a href="http://www.envfor.nic.in">www.envfor.nic.in</a> . | It has been complied.  |
| xiv  | A copy of the environmental clearance letter shall be marked to concern Panchayat /Zila Parishad, Municipal Corporation or Urban local body and local NGO, if any, from whom any suggestion/representation has been received while processing the proposal. A copy of the clearance letter shall also be displayed on company's website.   | Complied.  |



|       |   |                         |
|-------|---|-------------------------|
| xv    | A copy of the environmental clearance letter shall also be displayed on the website of the concerned State Pollution Control Board.<br>The EC letter shall also be displayed at the Regional Office, District Industry Sector and Collector's Office/Tehsildar's Office for 30 days.  | Complied.               |
| xvi   | The clearance letter shall be uploaded on the company's website. The compliance status of the stipulated environmental clearance conditions shall also be uploaded by the project, authorities on their website and updated at least once every six months so as to bring the same in public domain. The monitoring data of environmental quality parameter (air, water, noise, and soil) and critical pollutant such as PM10, PM2.5, SO2 and NO,, (ambient) and critical sectoral parameters shall also be displayed at the entrance of the project premises and mine office and in corporate office and on company's website. | Complied.               |
| xvii  | The project proponent shall submit six monthly compliance reports on status of compliance the stipulated environmental clearance conditions (both in hard copy and in e-mail) to view respective Regional Office of the Ministry, respective Zonal Office s of CPCB and the SPCB.   | Being complied in time. |
| xviii | The Regional Office of this Ministry located at Bhubaneswar shall monitor compliance of the stipulated conditions. The Project authorities shall extend full cooperation to the office) s) of the Regional Office by furnishing the requisite data/ information/monitoring reports.   | Shall be complied.      |
| xix   | The Environmental statement for each financial year ending 31 March in Form —V is mandated to be submitted by the project proponent for the concerned State Pollution Control Board as prescribed under the Environment (Protection) Rules,1986,as amended subsequently, shall also be uploaded on the company's website along with the status of compliance of EC conditions and shall be sent to the respective Regional Offices of the MoEF by E-mail.   | Being complied.         |
| 6.    | The proponent shall abide by all the commitments and recommendations made in the EIA/EMP report so also during their presentation to the EAC.   | Agreed                  |



|     |  |                      |
|-----|--|----------------------|
| 7.  | The proponent is required to obtain all necessary clearances/approvals that may be required before the start of the project.   | Agreed               |
| 8.  | The Ministry or any other competent authority may stipulate any further condition for environmental protection.  | Agreed               |
| 9.  | Failure to comply with any of the conditions mentioned above may result in the withdrawal of this clearance and attract the provisions of the Environment (Protection) Act, 1986.  | Agreed               |
| 10. | The above conditions will be enforced inter-alia, under the provisions of the Water (Prevention & Control of Pollution) Act, 1974, the Air (Prevention & Control of Pollution) Act, 1981. The Environment (Protection) Act, 1986 and the Public Liability Insurance Act, 1991 along with their amendments and Rules. The proponent shall ensure to undertake and provide for the costs incurred for taking up remedial measures in case of soil contamination, contamination of groundwater and surface water, and occupational and other diseases due to the mining operations. | It is being complied |
| 11. | The Environmental Clearance is subject to the outcome of the Writ Petition filed by M/S Bharat Coking Coal Limited (BCCL) in response to the closure orders issued by the Jharkhand State Pollution Control Board which is pending in the Jharkhand High Court.  | Agreed               |

-----





## **Annexure-A**

1. **Coal Production of the Cluster will be well within the limit for which environmental clearance has been granted.**

2. **OB BACKFILLING PROGRAMME**

At Godhur OC- After progressive extraction of coal upto V/VI/VII/VIII combined seam back filling of OB is going on.

At Gondudih KKC- progressive back filling of OB is going on after progressive extraction of total coal of all seams.

At East Bassuriya Colliery- Back filling will be done in continuous succession of total coal extraction.

Two handwritten signatures in blue ink are located in the lower-left quadrant of the page. The first signature is a simple, stylized mark, and the second is a more complex, cursive signature.


## Annexure-B

- **Plantation-** At Gondudih- Khas Kusunda Colliery Plantation has already been done by DFO, Dhanbad at about 10.5 Ha area of OB dump, and at present more than 26250 trees are there. 500 no. bamboo-gabion plantation have already been done. At about 2.0 Ha Ecological restoration site total about 6402 no. plants and plenty of grass-seeds have been planted successfully with encouraging results, and natural eco-system is being established there with increasing flora & fauna (Fig.2). At 2<sup>nd</sup>. eco-restoration site (about 1.79 Ha OB dump- area) about 2400 plants along with seeds of grass and shrubs have spread over since 2015-'16 successfully. And at 3<sup>rd</sup>. site, (about 3.0 Ha OB dump area) about 5322 plants and plenty of grass seeds have been planted and spreaded over during this monsoon successfully.

### PLANTATION/ECOLOGICAL-RESTORATION PROGRAMME

Plantation/Ecological Restoration Programme (Cluster-VI & part of Cluster-VII mines of Kusunda Area) :

| YEAR    | CLUSTER VI & CLUSTER VII(Part under Kusunda Area) | No.of saplings/plants   |
|---------|---|---|
| 2016-17 | 3.00 Ha(approx.)                                  | 5322 nos. already planted with plenty of grass seeds and plants seeds spreaded over |
| 2017-18 | 3.00 Ha(approx.)                                  | 7500  |
| 2018-19 | 3.00 Ha(approx.)                                  | 7500  |
| 2019-20 | 3.00 Ha(approx.)                                  | 7500  |
| 2020-21 | 6.00 Ha(approx.)                                  | 15000   |





Annexure-C

ENVIRONMENTAL MONITORING REPORT OF

CLUSTER – VI

(FOR THE Q.E. DECEMBER, 2016)



झारखण्ड राज्य प्रदूषण नियंत्रण पर्षद्  
Jharkhand State Pollution Control Board  
HIG-1, Housing Colony, Dhanbad-826001

Ph: 0326-2204933

Letter No.... 2650

Dated .... 6/7/13 .....

From,

Regional Officer,  
Dhanbad

To,

HOD (Env.),  
M/s. B.C.C.L.,  
Koyla Bhawan, Koyla Nagar,  
Dhanbad.


Sub: **Fixing up monitoring station/Sampling location of Air, Water & Noise.**

Sir,

With reference to you letter no. GM(Env.)/F-JSPCB/2013/783, dt. 06.07.2013 We have approved Air, Water & Noise monitoring Station/Sampling location after verification and return a copy of the map.

Encl-A/a.

Your's faithfully,

  
6/7/13  
(Dinesh Prasad Singh)  
Regional Officer.

Memo.....

Dhanbad, dated.....

Copy to: The Member Secretary, Jharkhand State Pollution Control Board for information  
& enclose a copy of the map for necessary action.

Encl-A/a.

(Dinesh Pd. Singh)  
Regional Officer.



**STRICTLY RESTRICTED**  
**FOR COMPANY USE ONLY RESTRICTED**

The information given in this report is not to be communicated either directly or indirectly to the press or to any person not holding an official position in the CIL / GOVERNMENT.

# **ENVIRONMENTAL MONITORING REPORT OF BHARAT COKING COAL LIMITED CLUSTER – VI**

**(FOR THE Q.E. DECEMBER, 2016)**

**E. C. no. J-11015/183/2011-IA.II (M) dated 26.08.2013-**

**March, 2017**



## **CMPDI**

ISO 9001 Company  
**Regional Institute-II**  
**Dhanbad, Jharkhand**

## CHAPTER-II

### AMBIENT AIR QUALITY MONITORING

#### 2.1 Location of sampling station and their rationale:

(as per G.S.R. 742 (E) dt. 25th December,2000)

##### 2.1.1 Ambient Air Quality Sampling Locations

#### I. CORE ZONE Monitoring Location

##### i) Basseriya Managers Office (A9): Industrial Area

The location of the sampling station is  $23^{\circ} 47'17''$  N &  $86^{\circ} 22'12''$  E. The sampler was placed at 1.5 m above the ground level of Safety Office. The station was selected to represent the impact of mining activities of Kusunda area, poor roads condition, heavy public traffic, burning of coal by the surrounding habitants.

#### II. BUFFER ZONE Monitoring Location

##### i) Nichitpur (A8) : Industrial Area

The location of the sampling station is  $23^{\circ} 48'20''$  N &  $86^{\circ} 21'30''$  E. The sampler was placed at 1.5 m above the ground level at Safety office of Nichitpur colliery.

##### ii) Pootki Balihari Office (A16): Industrial Area

The location of the sampling station is  $23^{\circ}45'18''$  N &  $86^{\circ}21'46''$ E The sampler was placed at 1.5 m above the ground level of Colliery Office.

#### 2.2 Methodology of sampling and analysis

Parameters chosen for assessment of ambient air quality were Particulate Matter ( $PM_{10}$ ), Particulate Matter ( $PM_{2.5}$ ), Sulphur Di-oxide ( $SO_2$ ) and Nitrogen Oxides ( $NO_x$ ). Respirable Dust Samplers (RDS) & fine particulates for  $PM_{2.5}$  sampler were used for sampling of  $PM_{10}$  &  $PM_{2.5}$  respectively at 24 hours interval once in a fortnight and the same for the gaseous pollutants. The samples were analyzed in Environmental Laboratory of CMPDI, RI-I, Asansol.

#### 2.3 Results & Interpretations

The results of Ambient Air Quality are presented in tabular form along with Bar chart for each monitoring station. The interpretations of different parameters are given below:



### 2.3.1 Ambient air quality

#### **Particulate Matter PM<sub>10</sub>**

In **core zone** under **Industrial area** varies from 86 to 112  $\mu\text{g}/\text{m}^3$  In  
**buffer zone** in **Industrial area** varies from 94 to 114  $\mu\text{g}/\text{m}^3$

#### **Particulate Matter PM<sub>2.5</sub>**

In **core zone** under **Industrial area** varies from 37 to 47  $\mu\text{g}/\text{m}^3$   
In **buffer zone** in **Industrial area** varies from 46 to 68  $\mu\text{g}/\text{m}^3$

#### **Sulphur Dioxide:**

In **core zone** under **Industrial area** varies from 11 to 13  $\mu\text{g}/\text{m}^3$   
In **buffer zone** in **Industrial area** varies from 11 to 14  $\mu\text{g}/\text{m}^3$

#### **Oxides of Nitrogen:**

In **core zone** under **Industrial area** varies from 23 to 28  $\mu\text{g}/\text{m}^3$   
In **buffer zone** in **Industrial area** varies from 24 to 29  $\mu\text{g}/\text{m}^3$

## AMBIENT AIR QUALITY DATA

Name of the Company: **Bharat Coking Coal limited**

Name of the Cluster : **Cluster – VI**

Year : **2016-17.**

Q.E.: **December 2016**


**Station Code/Name: (a) A9 Basseriya Managers Office**

**Category: Industrial**

**ZONE: Core**

**(a). Station Code/Name: A9 – Basseriya Managers Office Category: Industrial. <sup>1</sup>**


| Sl. No.        | Dates of sampling | PM 10 | PM 2.5 | SO <sub>2</sub> | NO <sub>x</sub> |
|----------------|-------------------|-------|--------|-----------------|-----------------|
| 1              | 06 - Oct -16      | 86    | 37     | 11              | 23              |
| 2              | 19 - Oct - 16     | 112   | 47     | 13              | 28              |
| NAAQ Standards |                   | 100   | 60     | 80              | 80              |



**Note:**

- All values are expressed in microgram per cubic meter.
- 24 hours duration.

<sup>1</sup> Report released by Shri Indranil De, Manager (Env), CMPDI, RI-1, Asansol,

Signed..........Dated 22.02.2017. Job No. 110310



## AMBIENT AIR QUALITY DATA

Name of the Company: **Bharat Coking Coal limited**  
 Name of the Cluster : **Cluster – VI**


Year : **2016-17.**  
 Q.E.: **December 2016**

**Station Code/Name:** (a) **A8 Nichitpur**  
 (b) **A16 Pootki Balihari Office**

**Category:** **Industrial.**  
**ZONE:** **BUFFER**

**(a). Station Code/Name:** **A8 – Nichitpur,** **Category:** **Industrial. <sup>2</sup>**


| Sl. No. | Dates of sampling | PM 10 | PM 2.5 | SO <sub>2</sub> | NO <sub>x</sub> |
|---------|-------------------|-------|--------|-----------------|-----------------|
| 1       | 20 - Oct -16      | 114   | 51     | 14              | 29              |
|         | NAAQ Standards    | 100   | 60     | 80              | 80              |



### Note:


- *All values are expressed in microgram per cubic meter.*
- *24 hours duration.*

<sup>2</sup> Report released by Shri Indranil De, Manager (Env), CMPDI, RI-1, Asansol,

Signed.....  .....Dated 22.02.2017. Job No. 110310

(b). Station Code/Name: A16 – Pootki Balihari Office, Category: Industrial.<sup>3</sup>

| Sl. No. | Dates of sampling | PM 10 | PM 2.5 | SO <sub>2</sub> | NO <sub>x</sub> |
|---------|-------------------|-------|--------|-----------------|-----------------|
| 1       | 13-Oct-16         | 94    | 46     | 11              | 26              |
| 2       | 07-Dec-16         | 99    | 68     | 12              | 24              |
| 3       | 28-Dec-16         | 94    | 53     | 13              | 26              |
|         | NAAQ Standards    | 100   | 60     | 80              | 80              |




**Note:**

- All values are expressed in microgram per cubic meter.
- 24 hours duration.



**Fig I: Ambient Air Monitoring Stations in Cluster- VI in Core & Buffer Zones**



---

## CHAPTER – III

### WATER QUALITY MONITORING

#### 3.1 Location of sampling sites (Refer Plate No. - II)

- i) **Mine Discharge of East Basseriya (MW6)**  
A sampling point is fixed to assess the effluent quality of Mine discharge. This location is selected to monitor effluent discharge in to Ekra Nala.
- ii) Drinking Water Quality at **Bansjora Borewell (GW6)**
- iii) Surface Water Quality at **U/S of Ekra Nala (SW14)**
- iv) Surface Water Quality at **D/S of Ekra Nala (SW15)**

#### 3.2 Methodology of sampling and analysis

Water samples were collected as per standard practice. The effluent samples were collected and analysed for four parameters on fortnightly basis. The drinking and Surface water samples were collected and analyzed for 25 & 17 parameters respectively on quarterly basis. Thereafter the samples were preserved and analysed at the Environmental Laboratory at CMPDI (HQ), Ranchi.

#### 3.3 Results & Interpretations

The results are given in tabular form along with the applicable standards. Results are compared with Schedule - VI, effluent prescribed by MoEF&CC. Results show that most of the parameters are within the permissible limits.



---

## WATER QUALITY DATA

(Effluent Water)

Name of the Company: **Bharat Coking Coal Limited** Year : **2016-17.**

Name of the Cluster : **Cluster - VI**

Month: **October, 2016.**

Name of the Stations & Code :

**1. MW6- Mine Discharge of East Basseriya**



### First Fortnight

| Sl. No. | Parameters             | MW6<br>(Mine Discharge ) | As per MOEF General Standards for schedule VI |
|---------|------------------------|--------------------------|---|
|         |                        | 06.10.2016               |   |
| 1       | Total Suspended Solids | 40                       | 100 (Max)                                     |
| 2       | pH                     | 8.54                     | 5.5 - 9.0                                     |
| 3       | Oil & Grease           | <2.0                     | 10 (Max)                                      |
| 4       | COD                    | 56                       | 250 (Max)                                     |

### Second Fortnight

| Sl. No. | Parameters             | MW6<br>(Mine Discharge ) | As per MOEF General Standards for schedule VI |
|---------|------------------------|--------------------------|---|
|         |                        | 19.10.2016               |   |
| 1       | Total Suspended Solids | 36                       | 100 (Max)                                     |
| 2       | pH                     | 7.84                     | 5.5 - 9.0                                     |
| 3       | Oil & Grease           | <2.0                     | 10 (Max)                                      |
| 4       | COD                    | 44                       | 250 (Max)                                     |

All values are expressed in mg/lit unless specified.

1   
2   
Analysed By

  
Approved By  
Dy. Technical Manager  
Env. Lab, CMPDI (HQ),  
(Authorized Signatory)

---

## WATER QUALITY DATA

(Effluent Water)

Name of the Company: **Bharat Coking Coal Limited** Year : **2016-17.**

Name of the Cluster : **Cluster - VI**

Month: **November, 2016.**

Name of the Stations & Code :

**1. MW6- Mine Discharge of East Basseriya**



### First Fortnight

| Sl. No. | Parameters             | MW6<br>(Mine Discharge ) | As per MOEF General Standards for schedule VI |
|---------|------------------------|--------------------------|---|
|         |                        | 05.11.2016               |   |
| 1       | Total Suspended Solids | 40                       | 100 (Max)                                     |
| 2       | pH                     | 7.71                     | 5.5 - 9.0                                     |
| 3       | Oil & Grease           | <2.0                     | 10 (Max)                                      |
| 4       | COD                    | 46                       | 250 (Max)                                     |

### Second Fortnight

| Sl. No. | Parameters             | MW6<br>(Mine Discharge ) | As per MOEF General Standards for schedule VI |
|---------|------------------------|--------------------------|---|
|         |                        | 29.11.2016               |   |
| 1       | Total Suspended Solids | 24                       | 100 (Max)                                     |
| 2       | pH                     | 8.36                     | 5.5 - 9.0                                     |
| 3       | Oil & Grease           | <2.0                     | 10 (Max)                                      |
| 4       | COD                    | 26                       | 250 (Max)                                     |

All values are expressed in mg/lit unless specified.

1   
2   
Analysed By

  
Approved By  
Dy. Technical Manager  
Env. Lab, CMPDI (HQ),  
(Authorized Signatory)

---

## WATER QUALITY DATA

(Effluent Water)

Name of the Company: **Bharat Coking Coal** Year : **2016-17.**

**Limited**

Name of the Cluster : **Cluster - VI**

Month: **December, 2016.**

Name of the Stations & Code :

**1. MW6- Mine Discharge of  
East Basseriya**

### First Fortnight

| Sl. No. | Parameters             | MW6<br>(Mine Discharge ) | As per MOEF General Standards for schedule VI |
|---------|------------------------|--------------------------|---|
|         |                        | 15.12.2016               |   |
| 1       | Total Suspended Solids | 40                       | 100 (Max)                                     |
| 2       | pH                     | 8.36                     | 5.5 - 9.0                                     |
| 3       | Oil & Grease           | <2.0                     | 10 (Max)                                      |
| 4       | COD                    | 28                       | 250 (Max)                                     |

### Second Fortnight

| Sl. No. | Parameters             | MW6<br>(Mine Discharge ) | As per MOEF General Standards for schedule VI |
|---------|------------------------|--------------------------|---|
|         |                        | 17.12.2016               |   |
| 1       | Total Suspended Solids | 28                       | 100 (Max)                                     |
| 2       | pH                     | 8.58                     | 5.5 - 9.0                                     |
| 3       | Oil & Grease           | <2.0                     | 10 (Max)                                      |
| 4       | COD                    | 24                       | 250 (Max)                                     |

All values are expressed in mg/lit unless specified.

  
Analysed By  
JSA/SA/SSA

  
Checked By  
Lab Incharge  
Env. Lab, RI-2, CMPDI

  
Approved By  
Dy. Technical Manager  
Env. Lab, CMPDI (HQ),  
(Authorized Signatory)



## **WATER QUALITY** **(SURFACE WATER- ALL PARAMETERS)**

Name of the Company: **Bharat Coking Coal Limited** Year : **2016-17.**  
 Name of the Cluster : **Cluster - VI** Period: **Q. E. December, 2016.**  
 Area : **Kusunda** Project: **East Cluster VI**  
 Stations: **Basseriya UGP** Date of Sampling:  
 1. Upstream in Ekra Nala SW-14 20/12/2016  
 2. Downstream in Ekra Nala SW-15 20/12/2016

| Sl. No | Parameter  | Sampling Stations |            |  |  | Detection Limit | IS:2296 – 1982<br>(Inland surface water)<br>Class C | BIS Standard & Method   |
|--------|--|-------------------|------------|--|--|-----------------|---|---|
|        |  | SW-14             | Sw-15      |  |  |                 |   |   |
| 1      | Arsenic (as As), mg/l, Max   | <0.002            | <0.002     |  |  | 0.002           | 0.2   | IS 3025/37:1988<br>R : 2003, AAS-VGA                            |
| 2      | BOD (3 days 27°C), mg/l, Max   | 2.4               | 2.6        |  |  | 2.00            | 300   | IS 3025 /44: 1993, R : 2003<br>3 day incubation at 27°C         |
| 3      | Colour ( Hazen Unit)   | colourless        | colourless |  |  | Qualitative     | 300   | Physical/Qualitative  |
| 4      | Chlorides (as Cl), mg/l, Max   | 112               | 114        |  |  | 2.00            | 600   | IS-3025/32:1988, R-2007,<br>Argentometric                       |
| 5      | Copper (as Cu), mg/l, Max  | <0.03             | <0.03      |  |  | 0.03            | 1.5   | IS 3025 /42 : 1992<br>R : 2009, AAS-Flame                       |
| 6      | Disolved Oxygen, min.  | 4.8               | 3.8        |  |  | 0.10            | 4   | IS 3025/38:1989,<br>R : 2003, Winkler Azide                     |
| 7      | Fluoride (as F) mg/l, Max  | 0.75              | 0.80       |  |  | 0.02            | 1.5   | APHA, 22 <sup>nd</sup> Edition<br>SPADNS                        |
| 8      | Hexavalent Chromium, mg/l, Max   | 0.019             | 0.027      |  |  | 0.01            | 0.05  | APHA, 22 <sup>nd</sup> Edition, 1,5 -<br>Diphenylcarbohydrazide |
| 9      | Iron (as Fe), mg/l, Max  | 1.124             | 1.070      |  |  | 0.06            | 50  | IS 3025 /53 : 2003,<br>R : 2009, AAS-Flame                      |
| 10     | Lead (as Pb), mg/l, Max  | <0.005            | <0.005     |  |  | 0.005           | 0.1   | APHA, 22 <sup>nd</sup> Edition<br>AAS-GTA                       |
| 11     | Nitrate (as NO <sub>3</sub> ), mg/l, Max                               | 0.087             | 0.053      |  |  | 0.50            | 50  | APHA, 22 <sup>nd</sup> Edition,<br>UV-Spectrophotometric        |
| 12     | pH value   | 6.74              | 8.22       |  |  | 2.5             | 6.5-8.5   | IS-3025/11:1983, R-1996,<br>Electrometric                       |
| 13     | Phenolic compounds<br>(as C <sub>6</sub> H <sub>5</sub> OH), mg/l, Max | <0.002            | <0.002     |  |  | 0.002           | 0.0005  | APHA, 22 <sup>nd</sup> Edition<br>4-Amino Antipyrine            |
| 14     | Selenium (as Se), mg/l, Max  | <0.002            | <0.002     |  |  | 0.002           | 0.05  | APHA, 22 <sup>nd</sup> Edition<br>AAS-GTA                       |
| 15     | Sulphate (as SO <sub>4</sub> ) mg/l, Max                               | 79                | 84         |  |  | 2.00            | 400   | APHA, 22 <sup>nd</sup> Edition<br>Turbidity                     |
| 16     | Total Dissolved Solids, mg/l, Max                                      | 700               | 707        |  |  | 25.00           | 1500  | IS 3025 /16:1984<br>R : 2006, Gravimetric                       |
| 17     | Zinc (as Zn), mg/l, Max  | <0.01             | <0.01      |  |  | 0.01            | 5.0   | IS 3025 /49 : 1994,<br>R : 2009, AAS-Flame                      |

  
 Analysed By  
 JSA/SA/SSA

  
 Checked By  
 Lab Incharge  
 Env. Lab, RI-2, CMPDI

  
 Approved By  
 Dy. Technical Manager  
 Env. Lab, CMPDI (HQ),  
 (Authorized Signatory)

All values are expressed in mg/lit unless specified.

# **WATER QUALITY** **(DRINKING WATER- ALL PARAMETERS)**

Name of the Company: **Bharat Coking Coal Limited** Year : **2016-17.**

Name of the Cluster : **Cluster - VI** Period: **Q. E. December, 2016.**  
Area : **Kusunda** Project: **East Cluster VI**  
**Basseriya UGP**

Stations: **1. Drinking Water from Bansjora borewell GW-6** Date of Sampling: **13/12/2016**

| SLNo | Parameter   | Sampling Stations |  |  | Detection Limit | IS:10500 Drinking Water Standards | Standard / Test Method                                |
|------|---|-------------------|--|--|-----------------|-----------------------------------|---|
|      |   | GW-6              |  |  |                 |                                   |   |
| 1    | Boron (as B), mg/l, Max   | <0.20             |  |  | 0.20            | 0.5                               | APHA, 22 <sup>nd</sup> Edition, Carmine               |
| 2    | Colour, in Hazen Units  | 11                |  |  | 1               | 5                                 | APHA, 22 <sup>nd</sup> Edition, Pt.-Co. Method        |
| 3    | Calcium (as Ca), mg/l, Max  | 25.6              |  |  | 1.60            | 75                                | IS-3025/40:1991, EDTA                                 |
| 4    | Chloride (as Cl), mg/l, Max   | 10                |  |  | 2.00            | 250                               | IS-3025/32:1988, R-2007, Argentometric                |
| 5    | Copper (as Cu), mg/l, Max   | <0.03             |  |  | 0.03            | 0.05                              | IS 3025/42 : 1992 R : 2009, AAS-Flame                 |
| 6    | Fluoride (as F) mg/l, Max   | 0.34              |  |  | 0.02            | 1.0                               | APHA, 22 <sup>nd</sup> Edition, SPADNS                |
| 7    | Free Residual Chlorine, mg/l, Min                                   | 0.03              |  |  | 0.02            | 0.2                               | APHA, 22 <sup>nd</sup> Edition, DPD                   |
| 8    | Iron (as Fe), mg/l, Max   | 1.825             |  |  | 0.06            | 0.3                               | IS 3025 /53 : 2003, R : 2009 , AAS-Flame              |
| 9    | Lead (as Pb), mg/l, Max   | 0.100             |  |  | 0.005           | 0.01                              | APHA, 22 <sup>nd</sup> Edition, AAS-GTA               |
| 10   | Manganese (as Mn), mg/l, Max  | 0.008             |  |  | 0.02            | 0.1                               | IS-3025/59:2006, AAS-Flame                            |
| 11   | Nitrate (as NO <sub>3</sub> ), mg/l, Max                            | 4.1               |  |  | 0.5             | 45                                | APHA, 22 <sup>nd</sup> Edition, UV-Spectrophotometric |
| 12   | Odour   | Agreeable         |  |  | Qualitative     | Agreeable                         | IS 3025 /05:1983, R-2012, Qualitative                 |
| 13   | pH value  | 8.34              |  |  | 2.5             | 6.5 to 8.5                        | IS-3025/11:1983, R-1996, Electrometric                |
| 14   | Phenolic compounds (as C <sub>6</sub> H <sub>5</sub> OH), mg/l, Max | <0.002            |  |  | 0.001           | 0.001                             | APHA, 22 <sup>nd</sup> Edition, 4-Amino Antipyrine    |
| 15   | Selenium (as Se), mg/l, Max   | <0.002            |  |  | 0.002           | 0.01                              | APHA, 22 <sup>nd</sup> Edition, AAS-GTA               |
| 16   | Taste   | Acceptable        |  |  | Qualitative     | Acceptable                        | APHA, 22 <sup>nd</sup> Edition, Taste                 |
| 17   | Sulphate (as SO <sub>4</sub> ) mg/l, Max                            | 9                 |  |  | 2.00            | 200                               | APHA, 22 <sup>nd</sup> Edition, Turbidity             |
| 18   | Total Alkalinity (CaCO <sub>3</sub> ), mg/l, Max                    | 116               |  |  | 4.00            | 200                               | IS-3025/23:1986, Titration                            |
| 19   | Total Arsenic (as As), mg/l, Max                                    | <0.002            |  |  | 0.002           | 0.01                              | IS 3025/ 37:1988 R : 2003, AAS-VGA                    |
| 20   | Total Chromium (as Cr), mg/l, Max                                   | 0.292             |  |  | 0.04            | 0.05                              | IS-3025/52:2003, AAS-Flame                            |
| 21   | Total Dissolved Solids, mg/l, Max                                   | 236               |  |  | 25.00           | 500                               | IS 3025 /16:1984 R : 2006, Gravimetric                |
| 22   | Total Hardness (CaCO <sub>3</sub> ), mg/l, Max                      | 124               |  |  | 4.00            | 200                               | IS-3025/21:1983, R-2002, EDTA                         |
| 23   | Turbidity, NTU, Max   | 3                 |  |  | 1.0             | 1                                 | IS-3025/10:1984 R-1996, Nephelometric                 |
| 24   | Zinc (as Zn), mg/l, Max   | <0.01             |  |  | 0.01            | 5.0                               | IS 3025/ 49 : 1994, R : 2009, AAS-Flame               |

  
Analysed By  
JSA/SA/SSA

  
Checked By  
Lab Incharge  
Env. Lab, RI-2, CMPDI

  
Approved By  
Dy. Technical Manager  
Env. Lab, CMPDI (HQ),  
(Authorized Signatory)

All values are expressed in mg/lit unless specified.

---

## CHAPTER - IV

### NOISE LEVEL QUALITY MONITORING

#### 4.1 Location of sampling sites and their rationale

i) **Basseriya Managers Office (N9)**

To assess the noise level in mine site, the noise levels were recorded in the mine area where all mining activities are in progress.

ii) **Nichitpur (N8)**

To assess the noise generated in the mines activity. Noise levels were recorded in the mines area

iii) **Kusunda OCP (N10)**

To assess the noise level in the industrial area,

iv) **Pootki Balihari Office (N16)**

To assess the noise level in the industrial area, noise levels were recorded during day time in the Mines area.

#### 4.2 Methodology of sampling and analysis

Noise level measurements in form of 'LEQ' were taken using Integrated Data Logging Sound Level Meter (NL-52 OF RION CO. Ltd. Make) during day time. Noise levels were measured for about one hour time in day time. Noise levels were measured in Decibels, 'A' weighted average, i.e. dB (A).

#### 4.3 Results & Interpretations

Ambient noise levels were recorded during day time and the observed values were compared with standards prescribed by MoEF&CC.

The results of Noise levels recorded during day time on fortnightly basis, are presented in tabular form along with the applicable standard permissible limits. The observed values in terms of LEQ are presented.

The observed values at all the monitoring locations are found to be within permissible limits.



## NOISE LEVEL DATA

Name of the Company: **Bharat Coking Coal Limited**      Year : **2016-17.**

Name of the Cluster : **Cluster -VI**

Month: **October, 2016.**

Name of the Stations & Code :

1. **Basseriya Managers Office (N9)**
2. **Nichitpur (N8)**
3. **Pootki Balihari Office (N16)<sup>1</sup>**

### (a) First Fortnight


| Sl. No. | Station Name/Code               | Category of area | Date       | Noise level dB(A)LEQ | *Permissible Limit of Noise level in dB(A) |
|---------|---------------------------------|------------------|------------|----------------------|--|
| 1       | Basseriya Manager's Office (N9) | Industrial area  | 06.10.2016 | 61.3                 | 75   |
| 2       | Pootki Balihari office (N16)    | Industrial area  | 13.10.2016 | 62.4                 | 75   |

### (b) Second Fortnight

| Sl. No. | Station Name/Code               | Category of area | Date       | Noise level dB(A)LEQ | *Permissible Limit of Noise level in dB(A) |
|---------|---------------------------------|------------------|------------|----------------------|--|
| 1       | Basseriya Manager's Office (N9) | Industrial area  | 19.10.2016 | 59.2                 | 75   |
| 2       | Nichitpur (N8)                  | Industrial area  | 20.10.2016 | 59.4                 | 75   |

*\*Permissible limits of Noise Level as per MOEF Gazette Notification No. GSR 742(E) dt. 25.09.2000 Standards for Coal Mines and Noise Pollution (Regulation and Control) Rules, 2000.*

\* Day Time: 6.00 AM to 10.00 PM.

<sup>1</sup> Report released by Shri Indranil De, Manager (Env), CMPDI, RI-1, Asansol, Signed..........Dated 22.02.2017. Job No. 110310

## NOISE LEVEL DATA

Name of the Company: **Bharat Coking Coal Limited** Year : **2016-17.**

Name of the Cluster : **Cluster -VI** Month: **December, 2016.**

Name of the Stations & Code :  
1. **Kusunda OCP (N10)**  
2. **Pootki Balihari Office (N16)<sup>2</sup>**

### a. First Fortnight

| Sl. No. | Station Name/Code            | Category of area | Date       | Noise level dB(A)LEQ | *Permissible Limit of Noise level in dB(A) |
|---------|------------------------------|------------------|------------|----------------------|--|
| 1       | Pootki Balihari office (N16) | Industrial area  | 07.12.2016 | 58.6                 | 75   |

### (b) Second Fortnight

| Sl. No. | Station Name/Code            | Category of area | Date       | Noise level dB(A)LEQ | *Permissible Limit of Noise level in dB(A) |
|---------|------------------------------|------------------|------------|----------------------|--|
| 1       | Pootki Balihari office (N16) | Industrial area  | 28.12.2016 | 59.8                 | 75   |

*\*Permissible limits of Noise Level as per MOEF Gazette Notification No. GSR 742(E) dt. 25.09.2000 Standards for Coal Mines and Noise Pollution (Regulation and Control) Rules, 2000.*

*\* Day Time: 6.00 AM to 10.00 PM.*




<sup>2</sup> Report released by Shri Indranil De, Manager (Env), CMPDI, RI-1, Asansol, Signed..........Dated 22.02.2017. Job No. 110310

Fig: Noise Level Monitoring Location of Cluster VI






## Location of Air & Noise Monitoring Stations in BCCL



BHARAT COKING COAL LIMITED  
Air & Noise Sampling Locations  
Monitoring Stations

**CMPDI**  
ISO 9001 Company

# Water Sampling Locations in BCCL



## INDEX

| Cluster | Surface Water (U/S, D/S) | Name of Mine / Jore       | Mineral Effluent Location | Sampling Water | Ground Water      | Sampling Location |
|---------|--------------------------|---------------------------|---------------------------|----------------|-------------------|-------------------|
| I       | SW1, SW2                 | Jamuria River             | Damoda Area               | GW1            | Glutway Village   |                   |
| II      | SW3, SW4                 | Khudia Nala               | Block II OCP              | GW2            | Joyrampur Village |                   |
| III     | SW4, SW5, SW6, SW7       | Nalla, Bagpigi Nalla      | Govindpur Colliery        | GW3            | Jogdih Village    |                   |
| IV      | SW8, SW11, SW9, SW10     | Katari River, Kumari Jore | Chotudih                  | GW4            | Kankanee Village  |                   |
| V       | SW12, SW13, SW15         | Jarian Nala, Ekra Nala    | Muddih                    | GW5            | Nichitpur         |                   |
| VI      | SW14, SW15               | Ekra Nala                 | East Bessuria UGP         | GW6            | Bansjora Borewell |                   |
| VII     | SW16, SW17               | Kari Jore                 | Dhansar UGP               | GW7            | Huriladih         |                   |
| VIII    | SW18, SW19               | Kashi Jore                | Jeenagora UGP             | GW8            | Ghanudih          |                   |
| IX      | SW19, SW20               | Kashi Jore                | Jeenagora                 | GW9            | Lodna             |                   |
| X       | SW21, SW22               | Damodar River             | Bhowrah North             | GW10           | Bhowrah South     |                   |
| XI      | SW23, SW24, SW25, SW26   | Nalla, Damodar River      | Bhagbandh UGP             | GW11           | Bhagbandh         |                   |
| XII     | SW27, SW28               | Kanti River               | Kapuria Murulidh          | GW12           | Kapuria           |                   |
| XIII    | SW29, SW30               | River                     | (20/21)                   | GW13           | Murilidh          |                   |
| XIV     | SW31, SW32               | Khudia Nala               | Lohapatti                 | GW14           | Lohapatti         |                   |
| XV      | SW5, SW32                | Khudia Nala               | Kharkharae UGP            | GW15           | Kharkharae        |                   |
| XVI     | SW33, SW34               | Khudia River              | Dahibari Damagora         | GW16           | Village           |                   |
| XVII    | SW35, SW36               | River                     | Colliery                  | GW17           | Chaptoria         |                   |



BHARAT COKING COAL LIMITED  
WATER SAMPLING LOCATIONS  
MONITORING STATIONS

CMPDI  
ISO 9001 Company

**Action taken :**

- (1) regular and sufficient water spraying by mobile tankers and through pipe lines is done at roads(haul roads, transportation roads, etc.), at all strategic dust generating points such as loading, un-loading, transfer points etc.
  - (2) covered coal transportation by trucks is already implemented
  - (3) plantation/eco-restoration at non-coal bearing/decoaled OB dump site is being done.
  - (4) making transportation road pucca and its regular maintenance
  - (5) use of dust extractors at drill m/c.
- etc.

**Note:** Pollution inventory of different sources within the area apart from the coal mining is required to be carried out for actual assessment of pollution load by mining and other sources.



## **ANNEXURE-D**

### **COMPLIANCE OF DHANBAD ACTION PLAN**

#### **(1) Covering of loaded transport vehicles**

It has been complied. The clause of covering of loaded coal transport vehicle has also been incorporated in the transport agreement/ contract.

#### **(2) Coal transport roads shall be made pucca**

In 2015-16 about 80 m pucca road near Kusunda Office has been constructed.

In 2016-17: about 57 m cement concrete road made from NH-32 connecting pt. to Kusunda-Godhur Office.

About 37 m cement concrete made of 15 no. road from NH-32 connecting pt. to Godhur W/Bridge.

#### **(3) All drillings to be done with dust containment and suppression systems. Sprinklers will be installed including at all coal stock & sidings**

**DUST EXTRACTOR:** Regarding drilling it has already been complied in all OC mines. Drill machines are having OEM fitted DUST EXTRACTION system.

**Complied.** Water sprinkling at all coal stock and sidings is being done by mobile water tankers and through pipe lines. Proposal for installation of fixed sprinklers at siding is under process.

#### **(4) MOBILE SPRINKLERS**

| Sl. no. | Mine                      | Haul road length in Km | No. of mobile sprinklers | Total Capacity(KL)                | Trips per day      |
|---------|---------------------------|------------------------|--------------------------|-----------------------------------|--------------------|
| 1       | Kusunda OC + Godhur mixed | 6.5-7.0                | 6                        | 1-20 KL each, 5-12KL each         | 35 trips/day       |
| 2       | Dhansar-Industry          | 5.4-5.8                | 6                        | 1-28 KL, 3-12KL each, 2-8 KL each | 40 trips/day       |
| 3       | Gondudih KKC              | 5.0-6.0                | 4                        | 10 KL each                        | 15 trips each/day, |
| 4.      | East Bassuriya            | 2.5-3.0                | 1                        | 12KL                              | 9 trips each/day   |

#### **(5) The direction of surface run-off of the premises of collieries shall be diverted to created water bodies.**

Creation of water bodies in coal bearing area will pose safety threats to nearby mine and it will be violation of mines act. This will also create grave danger of inundation of the adjacent mines since the mines are 100 years old and interconnected with each other. So this action cannot be complied.

However to catch run-off water in colonies proposal for Rain water Harvesting in colonies is under process

#### **(6) Dealing of mine fires**

A Master plan for Dealing with fires and subsidence and rehabilitation in the Leasehold of BCCL has been approved by Govt. of India vide letter no- 22020/1/2005-CRC dated 12 08 09. In fire patch of V/VI/VII/VIII seam of Gareria Secn. At East Bassuriya about 1, 70,000 cu.m. mitti and non-combustible material has been filled, rest will be filled by quarry OB.

In Kusunda OC, fiery coal patches are being dug out for the purpose of dealing with fire and combustible materials are extracted out to save the coal from burning and to stop further spread of the fire. Once the total fiery coal is dug-out/excavated there will be no more chance of re-starting of fresh/ spreading of fire into other areas.

At Alkusa mine, measures have been taken as per CMR'57 and DGMS Guidelines to control fire and entrances have been filled/sealed to stop ingress of air into fire affected area. At Dhansar-Industry Colliery complete digging of fiery coal of X seam by OC method is being done with water jet through pipe line and submersible pump installed at Industry 2Pit in addition by fire-tender.

#### **(7) The waste water shall be passed through oil separator-cum-filtration system**

-- It shall be complied

#### **(8) The removed OBs shall be utilized for low land filling or for making roads.**

**Complied.** Removed OB is used for low land filling and for making roads as and when required.

#### **(9) Tree plantation on the dumps**

**Complied.** At Gondudih- Khas Kusunda Colliery Plantation has already been done by DFO, Dhanbad at about 10.5 Ha area of OB dump, and at present more than 26250 trees are there. 500 no. bamboo-gabion plantation have already been done. At about 2.0 Ha Ecological restoration site total about 6402 no. plants and plenty of grass-seeds have been planted successfully with encouraging results, and natural eco-system is being established there with increasing flora & fauna. At 2<sup>nd</sup>. eco-restoration site (about 1.79 Ha OB dump- area) about 2400 plants along with seeds of grass and shrubs have spread over since 2015-'16 successfully. And at 3<sup>rd</sup>. site, (about 3.0 Ha OB dump area) about 5322 plants and plenty of grass seeds have been planted and spreaded over during this monsoon successfully.

#### **(10) All hazardous wastes shall be disposed off**

**Complied.**

1. All units have applied for authorization as per Hazardous Wastes (Management, Handling and Trans boundary Movement) Rules.
2. Burnt/used oil is disposed off as per rule.
3. Disposal of Hazardous waste, burnt Oil / batteries is being done through E-auctioning to authorized recycler/ re-processor having valid authorization from CPCB/ SPCB. Return are also being filed.

#### **(11) Monitoring and Reporting six monthly**

Monitoring work has been done by CMPDI, Dhanbad as per work order issued by BCCL HQ.

#### **(12) Introduction of GIS/ GPS**

CMPDI, HQ has been given the job of satellite surveillance of the Jharia coal field through NRSA Hyderabad and the information is being uploaded in the website.



**ANNEXURE-E**

**KUSUNDA AREA**

**Status of Periodical Medical Examination & Training**

| <b>Mines under Cluster-VI</b>                                    | <b>Total PME done for the period April'16 to March'17</b> | <b>Training done at GVTC for the period April'16 to March'17</b> |
|--|---|--|
| <b>Bassuriya, East Bassuriya, Godhur , Gondudih Khas Kusunda</b> | <b>641</b>  | <b>633</b>   |

| <b>Recognition of Prior Learning (RPL) by NSDC</b> | <b>RPL Training done for Cluster-VI mines</b> |
|--|---|
|  | <b>681</b>                                    |







**Figure 1** *Stone Pitching/embankment at Kari Jore near Godhur Colliery.*

**Fig. 2 : Eco-restoration at OB Dump at Gondudih Khas Kusunda Colliery**





## **CSR, R&R AND TRANSPORTATION PLAN OF CLUSTER-VI GROUP OF MINES**

***As per the condition [Specific condition : A(xxxv)] of Environment Clearance of Cluster VI group of Mines of BCCL granted by Ministry of Environment & Forest, Govt. of India vide order no.: J-11015/183/2011-IA.II(M), dated 26<sup>th</sup>. August, 2013.***



## CSR ACTIVITIES OF BCCL

### **Corporate Social Responsibility (CSR) in Adjoining Villages**

As per Corporate Social Responsibility policy of Coal India, the community facilities is being provided by Bharat Coking Coal Limited. The following areas are being covered:

- Poor and needy section of the society
- Within the radius of 15 km for every project and areas including HQ

### **Scope of CSR:**

- a) Education
- b) Water supply
- c) Health care
- d) Environment
- e) Social empowerment
- f) Infrastructure for villages
- g) Sports and culture
- h) Generation of Employment and setting up of co-operatives
- i) Infrastructure support
- j) Grant/donation/financial assistance/sponsorship to reputed NGOs of the society/locality doing/involved in the uplifting of standard of the society
- k) Miscellaneous: Adoption of villages for carrying out the activities like infrastructural development, collection of old clothes from employees and distribution in the nearby villages

**Bharat Coking Coal Limited (BCCL)** is committed to good corporate citizenship and makes constant efforts to build and nurture long lasting relationships with members of the society in general and its peripheral communities in particular.

BCCL is taking up activities from the HQ level and through its administrative areas for the implementation of CSR activities. For this purpose A CSR cell is functioning at HQ. which is headed by General Manager(CSR) under the direct control of Director(Personnel) of the company.

### **The CSR activities presently being done by BCCL**

- To meet the acute shortage of drinking water in peripheral villages' drinking Water is provided through deep borewells, tubewells, pumps/motors, in the peripheral villages of BCCL. Water supply through pipeline, through water tanker is provided also to the villages. Mine water is supplied after proper filtration in Filter Plants.
- **Education:** BCCL adopts a multi-pronged approach to promote quality education in backward areas. The measures taken by BCCL comprise Construction, Extension, and Renovation of school buildings etc are done to promote quality education in the nearby villages. BCCL is Extending financial aid for educational facilities to 83 nos. Private Committee Managed schools. Measures are taken to promote women literacy and carrier development.
- **Health Care:** BCCL Conducts medical/health camps for dwellers of peripheral villages for rendering free medical consultancy. CSR Clinics, wellness clinics, artificial limbs centers are organized for the benefit of the needy section of the society.. Mobile medical vans are deployed as special arrangement for medical services. AIDS awareness camps are organized



as special drive to develop awareness and to render free consultancy. In Kusunda Area many medical /health camps in peripheral villages and in collieries and various awareness programmes have already been conducted, and is being conducted regularly by Area Medical Team.

- **Occupational health:** awareness programme are organized.
- **Other Welfare Activities:** this includes Construction / renovation of Community Halls, construction / repair of roads, construction of Health-sub centres, construction of drain, construction of Chhat Ghat in the ponds, Construction of Boundary wall, providing Choupal for community gatherings, etc.
- **Mashla Chakki centres :** Mashla Chakki centres has been established with machines to promote self employment.
- **Sports & Cultural:** Various activities are organized to propagate sports and cultures. Sports/games items and instruments are also provided with play ground.
- **Village adoption:** Lahbera – A SC/ST village nearby Dhansar Mine has been adopted for its all round development and a number of development activities have been carried out including school, health care and Ambulance facility, Mashla Chakki Centre, Community Centre, Play ground, etc.

#### **Upkeep and Maintenance of Assets**

Before any capital investment made the concerned State Government and the local representative of the society, took an undertaking from the representatives of the local community that they would be responsible for the maintenance of the assets.

#### **IN KUSUNDA AREA [Cluster- VI & VII (part)] :**

A lot of CSR activities have been done in the peripheral villages in the field of **medical and civil and welfare**.

#### **Medical CSR :**

#### **Health Campaigning at surrounding villages by MMV (Mobile Medical Van) :**

| <b><u>Year</u></b> | <b><u>No. of MMV camps</u></b> | <b><u>Beneficiaries</u></b> |
|--------------------|--------------------------------|-----------------------------|
| 2013-'14           | 298                            | 11,171 patients             |
| 2014-'15           | 306                            | 11,884 patients             |
| 2015-'16           | 380                            | 11,013 patients             |

| <b><u>Village Health Camps-</u></b> | <b><u>No. of camps</u></b> | <b><u>Beneficiaries</u></b> |
|-------------------------------------|----------------------------|-----------------------------|
| 2016-'17                            | 262                        | 6989                        |

#### **Special Health Camps in**

|                          |   |                         |
|--------------------------|---|-------------------------|
| 2015-'16                 | 5 | 354 patients            |
| 2016-'17                 | 2 | 62 children + 6 patient |
| CSR Clinic :2015-'16     |   | 5842 patients           |
| 2016-'17                 |   | 2954 patients           |
| Wellness Clinic 2015-'16 |   | 6244 patients           |
| 2016-'17                 |   | 3922 patients           |



In 2013-'14 , 2014-'15 , 2015-16 and 2016-17 following civil work have been completed under CSR

Activity

- Construction of compound wall for Lahbera School at Dhansar -- work completed
- Deeping of Pond at Lahbera Basti at Dhansar -- work completed
- Constr. of pcc road from Dom tola to Kali Mandir at Barki Bowa Village -- work completed
- Constr. of pcc road from near house of Vikash Rajak to main road at Satitand Village -- work completed
- Constr. of pcc road from Parduman Singh Chowk to near house of Sri Kishore Pandey at Ranguni Panchayat -- work completed
- Constr. of Yatri shed at Dutta Tola near Hanuman Mandir of Ranguni Panchayat -- work completed
- Constr. of boundary wall , Chabutra and a shed near Gram Dewata at Dhansar -- work completed
- Construction of PCC road in Lahbera Basti at Dhansar -- work completed
- Construction of 318 toilets in 179 schools in Chaibasa has been undertaken by Kusunda Area under the Pradhan Mantri Swatchh Vidyalaya Yojana . Construction of toilets in 25 boys' school, 15 girls' schools and 139 Co-education School have been undertaken. -- Out of 318, 245 toilets have been completed Upto March'2017. Rest are under construction.

Financial assistance by Kusunda Area to Private Committee managed Schools in villages during the financial year 2016-'17:

(fig.provided by Area Finance Deptt., Kusunda Area)

| Name of School  | Total Amount (Rs.) in 2016-'17 |              |              |              |
|---|--------------------------------|--------------|--------------|--------------|
|   | 2013-'14                       | 2014-15      | 2015-16      | 2016-17      |
| L.P.School, Dhansar ;<br>Vikash H.A.School, Bassuriya ;<br>Bal Vikash P.V.Industry Colly.;<br>Sanjay Gandhi S.M.V.,Godhur;<br>Gandhi M.K.E.S.E.,Bassuriya;<br>Madhya Vidyalay, Kurmidih ;<br>Bassuriya Vidyalay,Bassuriya;<br>Shishu Vikash M.Vidyalay, Godhur;<br>J.N.Vidyalay, Gondudih;<br>DAV School, Kusunda | 12,67,500.00                   | 29,73,750.00 | 29,73,750.00 | 24,59,250.00 |

## STATUS OF JHARIA MASTER PLAN DOVETAILED WITH ENVIRONMENT CLEARANCE CONDITIONS

### **Rehabilitation and Fire control measures**

#### **Socio-economic Survey :**

Survey of fire affected families (non-BCCL) at Kusunda Area has been nearly completed by JRDA and distribution of ID Card has been partially done by JRDA.

#### **Accommodation provided in Satellite Township:**

- Till about 1152 quarters at newly constructed colonies situated at East Bassuriya , Jagjiwan Nagar and Karmik Nagar have been allotted to the BCCL employees residing at coal bearing/fire affected areas in different collieries under Kusunda Area and out of which 480 employees have been shifted, and 480 houses in coal bearing/fire affected area has been demolished. More quarters are under construction for phasewise shifting of employees.
- In temporary rehabilitation site at decoaled zone of East Bassuriya about 28 PAF/encroachers have been shifted.
- Non-BCCL families are being shifted by JRDA.


#### **Status of fire dealing :**

Under Master Plan, many Fire schemes have been formulated / prepared /implemented for dealing fires sites spread in collieries of BCCL. Further for expediting the fire dealing process, excavation methods has been resorted to by deploying Hired HEMM at various mines of BCCL. Total digging out of fiery coal has been adopted for dealing of fire.

In fire patch of V/VI/VII/VIII seam of Gareria Secn. at East Bassuriya, about 1,70,000 cu.m. mitti and non-combustible material has been filled, rest will be filled by quarry OB .

At Kusunda Colliery total firey coal are being dug out as a measure of fire dealing with the deployment of hired HEMM, and at Ena OC, after restart, total firey coal will be dug out . The underground workings of Alkusa Colliery has been sealed due to fire threats after taking measures to control UG fire as per CMR'57 and DGMS guidelines. The coal reserve of Alkusa Colliery will be extracted from Kusunda OC side. For control and monitoring of threat of subsidence at fire affected area within Godhur lease hold special attention has been made by mine management, at Godhur OC total firey coal are being dug out as a measure of fire dealing with the deployment of hired HEMM. At Dhansar-Industry Colliery complete digging of fiery coal of X seam by OC method is being done with water jet through pipe line and submersible pump installed at Industry 2Pit in addition by fire-tender.

---







## COAL TRANSPORTATION

### Coal Despatch


The coal produced from the working faces of the mine are transported and dumped in the coal stock yard and thereafter it is transported to different plants contractually under road sale, or transported to the railway sidings for despatch to different organisations (steel/power/fertilizer plants etc).

In Kusunda Area of BCCL, two railway sidings are there namely KDS-K and KDS II. BNR railway siding under Bastacola Area is also being used for coal despatch by railway wagon.

### Av. Distance of Sidings from Mines



[ At present Godhur UG is discontinued ]




**Average distance of different Power/Steel/fertilizer plants etc from Kusunda**

| Name of organisation              | Avg distance in km |
|-----------------------------------|--------------------|
| Chandrapura Thermal Power station | 43                 |
| Harduaganj Thermal Power station  | 1071               |
| Parichha Thermal Power station    | 948                |
| Mejia Thermal Power station       | 105                |
| Koderma Thermal Power station     | 123                |
| DSTP                              | 98                 |
| Pradhan Mantri Rajiv Gandhi       | 1409               |
| NFL(Nangal dam)                   | 1478               |
| Budge Budge                       | 1478               |
| NFL                               | 1287               |
| NFL (BTI)                         | 1497               |

**MINE WISE TOTAL COAL DESPATCH**

| YEAR    | DESPATCH | MINES UNDER CLUSTER-VI |                |           |              |
|---------|----------|------------------------|----------------|-----------|--------------|
|         |          | Godhur                 | East Bassuriya | Bassuriya | Gondudih KKC |
| 2013-14 | Rail     | 34524                  | 75734.76       | 75939.96  | 920230.73    |
|         | Road     | 58476                  | 17922.95       | 13310.21  | 158851.97    |
|         | Total    | 93000                  | 93657.71       | 89250.17  | 1079082.7    |
| 2014-15 | Rail     | 32047                  | 158749         | 4995      | 174200       |
|         | Road     | 23005                  | 0.00           | 0.00      | 6032         |
|         | Total    | 55052                  | 158749         | 4995      | 180232       |
| 2015-16 | Rail     | 423345.14              | 14742          | 0.00      | 524138.1     |
|         | Road     | 11057.68               | 0.00           | 0.00      | 20790.52     |
|         | Total    | 434402.82              | 14742          | 0.00      | 544928.62    |
| 2016-17 | Rail     | 721026.54              | 231008.26      | 0.00      | 928136.09    |
|         | Road     | 181471.18              | 12110.15       | 0.00      | 181635.77    |
|         | Total    | 902497.72              | 243118.41      | 0.00      | 1109771.86   |



-----



# **DELINEATION OF SURFACE COAL FIRE IN THE JHARIA COALFIELD, DHANBAD, JHARKHAND USING REMOTE SENSING DATA**

**GEOSCIENCES GROUP  
RS & GIS APPLICATIONS AREA  
NATIONAL REMOTE SENSING CENTRE  
INDIAN SPACE RESEARCH ORGANISATION  
DEPT. OF SPACE, GOVT. OF INDIA  
HYDERABAD-500 037  
MARCH, 2014**





# DELINEATION OF SURFACE COAL FIRE IN THE JHARIA COALFIELD, DHANBAD, JHARKHAND USING REMOTE SENSING DATA

## **Report for**

**BHARAT COKING COAL LIMITED (BCCL)**

**(A SUBSIDIARY OF COAL INDIA LTD.)**

**ENVIRONMENT DEPARTMENT, KOYLA BHAWAN**

**KOYLA NAGAR, DHANBAD – 826 005, JHARKHAND**

**GEOSCIENCES GROUP**

**RS & GIS APPLICATIONS AREA**

**NATIONAL REMOTE SENSING CENTRE**

**INDIAN SPACE RESEARCH ORGANISATION**

**DEPT. OF SPACE, GOVT. OF INDIA**

**HYDERABAD-500 037**

**MARCH, 2014**



| DOCUMENT CONTROL SHEET |                               |   |   |  |
|------------------------|-------------------------------|---|---|--|
| 1.                     | Security Classification       | Official only   |   |  |
| 2.                     | Distribution                  | BCCL and NRSC/ISRO/DOS  |   |  |
| 3.                     | Report / Document Version     | (a) Issue no.<br>01   | (b) Revision & Date<br>00   |  |
| 4.                     | Report / Document Type        | Report on Coal fire study.  |   |  |
| 5.                     | Document Control Number       | NRSC-RSAA-GSG-ARR-2014-TR-608   |   |  |
| 6.                     | Title                         | DELINEATION OF SURFACE COAL FIRE IN THE JHARIA COALFIELD, DHANBAD, JHARKHAND USING REMOTE SENSING DATA  |   |  |
| 7.                     | Particulars of collation      | Pages<br>47   | Figures<br>18   | Tables<br>6<br>References<br>10                                  |
| 8.                     | Author(s)                     | Shri Priyom Roy S/E 'SC'  |   |  |
| 9.                     | Affiliation of authors        | Geosciences Group,<br>RSA, National Remote Sensing Centre   |   |  |
| 10.                    | Scrutiny Mechanism            | Compiled by<br>Shri Priyom Roy<br>S/E 'SC'  | Reviewed by<br>Dr. K. Vinod Kumar,<br>S/E 'SG',<br>Group Head,<br>Geosciences Group | Approved by<br>Dr. P. G. Diwakar,<br>Dy. Director<br>(RS&GIS-AA) |
| 11.                    | Originating unit              | Geosciences Group, RSA.   |   |  |
| 12.                    | Sponsor(s) / Name and Address | Bharat Coking Coal Limited (BCCL)<br>(A Subsidiary of Coal India Ltd.)<br>Environment Department, Koyla Bhawan<br>Koyla Nagar, Dhanbad – 826 005, Jharkhand   |   |  |
| 13.                    | Date of Initiation            | September, 2013.  |   |  |
| 14.                    | Date of Publication           | 22nd April, 2014  |   |  |
| 15.                    | Abstract (with Keywords)      | This report describes about the coal mine fire areas mapped using thermal channel of satellite sensor such as ASTER (90m resolution) in Jharia coal field. Relative radiant temperature image derived from raw thermal data of 2012 is thresholded by two different methodologies to delineate the fire zones in Jharia coal field for the year 2012. |   |  |

## **EXECUTIVE SUMMARY**

Coal fire is a serious problem in Jharia coal field, where high grade coal is gradually combusted due to these fires. The combined act of surface and sub-surface fires has endangered the environmental stability of Jharia coal field. Coupled with the ecological changes instigated by open cast mining, the landscape in and around Jharia have changed drastically over the years. Remote sensing data have immense potential in earth sciences and other disciplines mainly because of its synopticity and repetivity. In the present study, delineation of coal fire, which is the major environmental problem in coal mining areas, is addressed. Thermal bands in ASTER (90m resolution) have been used to demarcate the coal mine fire areas from non fire areas. For this study, ASTER data of May, 2012 have been used. The band 13 (10.25-10.95  $\mu\text{m}$ ) of ASTER data is used to derive the relative radiant temperature. The study reflects that, compared to 2006, the eastern flanks (Lodna, Tisra areas) and the western flank (Nadkhurkee, Shatabdih area) show diminished fire presence. New fire areas are observed in the northern flank in the areas around Katras and Gaslitand. Among all the colliery areas, Kusunda area is most affected by coal mine fire. The coal mine fire and non fire areas are further verified on the ground and fire temperature on the ground was measured using the handheld infrared thermometer. The final coal mine fire map of Jharia coal field is prepared by using iterative as well as statistical thresholding techniques with the information collected from ground.



## ***CHAPTER I***

### **INTRODUCTION**

Coal fire is a perennial problem in Jharia coal field (JCF) covering 447 sq. km. area in the Dhanbad district of Jharkhand state. Subsurface and surface coal fires are a serious problem in many coal-producing countries. The severity and extent of mine fires in some of the Indian coalfields, particularly Jharia and Raniganj coalfields are quite alarming. Combustion can occur either within coal or in coal dumps on the surface. Considerable economic loss and environmental problem arises due to this coal fire hazard. Coal fire burns valuable coal and also creates difficulties in mining by increasing the cost of production or making existing operations difficult. Noxious gases like sulphur dioxide, nitrogen oxide, carbon monoxide, carbon dioxides, which are the result of coal burning processes often affect the immediate surroundings of an active coal fire (Gangopadhyay, 2003). These greenhouse gases not only affect local atmosphere but also play a crucial role in the damages, found associated with coal fire such as land surface subsidence and surface cracking. Coal fires are caused by oxidation of coal but the reaction involved in oxidation of coal is not understood till date. Broadly, the potential for spontaneous combustion lies in its ability to react with oxygen at ambient temperature. This occurs through the absorption of oxygen at the surface of the coal resulting in an exothermic reaction. As a consequence the temperature of coal rises and if temperature reaches threshold temperature, ranging between 80<sup>0</sup> to 120<sup>0</sup>C, a steady reaction starts, which produces carbon dioxide. Temperature keeps on increasing once CO<sub>2</sub> is started to form and at 2300<sup>0</sup>C exothermic reaction become rapid. It is known that high ranking coals (high carbon content) are more fire prone, though the reason behind this is not clear. Another important parameter, which controls fire, is the size of the particles. Larger the effective area of coal (fire particles) more rapidly the reaction proceeds. Cracks, fissures play a role like positive catalysts to coal oxidation by supplying slowly oxygen / air through their conduits.

Coal mining in Jharia Coal Field (JCF) started way back in 1895. History of fire in Jharia Coal Field dates back to 1916 when the first incidence of fire was reported from XIV seam of Bhowrah colliery. JCF was nationalised in 1972 and over

the decades, the fire has spread or been contained but never extinguished. The combinations of underground fires and subsidence have affected vast areas of JCF.

## 1.1 Background

In order to manage effectively the coal fire menace, it is essential to know the exact location and extent of the fire affected areas. Remote sensing technique in thermal band offers a cost-effective and time-saving technology for mapping various geoenvironmental / hazardous features like coal fires, forest fires, oil well fires, volcanic eruptions etc. These features are identified in thermal bands as high temperature anomalous areas. Hot bodies on the surface of the earth mostly emit radiation in this band. NRSC has carried out coal fire mapping projects in the past; conducting an airborne campaign in 1989 and using Landsat-5 TM data in 1995 (Bhattacharya *et. al.*, 1995), over Jharia coalfield, Jharkhand and using data for 2001 over Raniganj coalfield, West Bengal. Further another project was executed in 2006, in which coal fire of the Jharia Coalfield was mapped for 2003 and 2006, using ETM+ and ASTER data respectively. In view of the past experiences, based on the letter (Ref. no. BCCL/DT(OP)/F-13) from Director (Tech.) BCCL, Operations, BCCL addressed to Director, NRSC with consequent discussions on the 8th of January, 2013 (Minutes recorded in letter vide BCCL/DT(OP)/F-ENV/2012/148(A)) a project was formulated to take up Coal fire study of the Jharia Coal Field using space-borne remote sensing techniques to study the status of coal-fire as of the year 2012. The formal Memorandum of Understanding between BCCL and NRSC was signed on 15th of July, 2013.

## 1.2 Objectives

The following objectives are formulated on the basis of the above mentioned background:

- I. Mapping of Coal fire in the study area based on pixel integrated relative radiant temperature derived from ASTER data of 2012.
- II. Comparison of the change in the coal fire distribution in the Jharia coalfield within the period of 2006 and 2012.

### 1.3 Study Area

Jharia Coalfield is located in the Dhanbad district of Jharkhand state (Figure 1) and it is named after the main mining area of Jharia. It is situated in the heart of Damodar River valley and is about 250 km NW of Kolkata. The coalfield is contained roughly within latitudes  $23^{\circ} 38' \text{ N}$  and  $23^{\circ} 52' \text{ N}$  and longitudes  $86^{\circ} 08' \text{ E}$  and  $86^{\circ} 30' \text{ E}$ .





Figure1: Study area



The generalised stratigraphy of this area is mentioned below (after Saraf, et al., 1995).

| FORMATION           | LITHOLOGY  | MAXIMUM THICKNESS |
|---------------------|--|-------------------|
| Supra Panchet       | Red and Grey sandstones and shales                                   | 300m              |
| Panchet             | Micaceous Yellow and Grey sandstones, Red and Greenish shales        | 600m              |
| Raniganj            | Grey and Greenish soft feldspathic sandstones, shales and coal seams | 1050m             |
| Ironstone Shales    | Dark carbonaceous shales with ironstone bands                        | 360m              |
| Barakar             | Coarse and medium Grey and white sandstones, shales and coal seams   | 630m              |
| Talchir Boulder Bed | Coarse sandstones above and Greenish shales below                    | 300m              |

Figure 2 : Geological map of Jharia coal field, Dhanbad, Jharkhand (published by CMPIDL)



# REMOTE SENSING DATA ANALYSIS

## 4.1 Principles of thermal remote sensing

All matter at temperature above absolute zero (0° Kelvin) emits electromagnetic radiation continuously. The temperature of the earth materials and high temperature phenomenon can be estimated based on the thermal emission from these materials. Max Planck, using his quantum theory, developed a relation between spectral radiance, wavelength of the emitted radiation and temperature for the blackbody. The Planck's equation for black body is given in equation -1.

$$L_{\lambda} = \left[ \frac{2\pi hc^2}{\lambda^5} \right] * \left[ \frac{1}{e^{\frac{hc}{\lambda \kappa T}} - 1} \right] \dots\dots\dots (1)$$

Where

$L_{\lambda}$  = Spectral radiance of selected thermal infrared band (W/m<sup>2</sup>/Sr)

$\lambda$  = Wavelength (m) in selected thermal infrared band

$T_{\text{rad}}$  = Radiant Temperature (°K)

$h$  = Planck's constant (6.63 x 10<sup>-34</sup> joule

sec)  $c$  = Speed of light (3.0 x 10<sup>8</sup> m/sec)

$\kappa$  = Boltzmann constant (1.38 x 10<sup>-23</sup> joules/k)

Equation (1) can be rearranged as follows

$$T_{\text{rad}} = \frac{C_2}{\lambda \ln\left(\frac{\epsilon C_1}{\pi L_{\lambda} \lambda^5} + 1\right)} \dots\dots\dots (2)$$

Where

$C_1 = 2\pi hc^2 = 3.742 \times 10^{-16} \text{ Wm}^2$

$C_2 = hc/k = 0.0144\text{mK}$

$\epsilon$  = Emissivity

In equation - 2, wavelength may be considered as the mean wavelength of the spectral region under investigation. Once the corrected spectral radiance ( $L_{\lambda}$ ) is

known for a pixel, it can be substituted to equation – 2 to compute radiant temperature value. The radiant temperature is defined as the equivalent temperature of a black body which would give the same amount of radiation, as obtained from a real body. The radiant temperature ( $T_R$ ) depends on actual temperature of surface element i.e. kinetic temperature ( $T_K$ ), emissivity ( $\epsilon$ ) and transmissivity of atmosphere (Gupta, 2003). Emissivity ( $\epsilon$ ) for a blackbody is 1 and for most materials it is less than 1 ranging generally between 0.7 and 0.96. So the kinetic temperature of natural materials is always higher than the radiant temperature.

In the present study, coal fires are mapped on the basis of their temperature from the back ground non fire zone. Coal fires are very high temperature surface elements with high thermal flux and are very close to black body in terms of their thermal behaviour. However emissivities of fire zones are dependent on several factors such as presence of moisture in coal and the total carbon concentration in coal etc. Coal fires with high thermal flux are very restricted in terms of surface extent. Therefore total thermal flux is  $8100\text{m}^2$  (in case of ASTER Data) represent the average thermal flux emanating from both coal fire zones and non coal fire area of given pixel. The emissivity and radiant temperature of a pixel containing fire depends on the entire contributing element within the pixel. If pixel averaged radiant temperature remains quite higher than the pixel containing no fire (background), then only coal fire zones can be delineated.

## **4.2 Methodology**

### **4.2.1 Processing of ASTER Data**

In the present study, Multispectral Advanced Thermal Emission and Reflection Radiometer (ASTER) data dated May, 2012 is acquired for coal fire mapping. ASTER provides five thermal channels in the thermal region within  $8.125 - 11.65 \mu\text{m}$  wavelength domain. Multi channel ASTER data is very useful to derive emissivity by using temperature emissivity algorithm and thereby allows seeing the thermal anomaly within the range of entire thermal domain of ASTER. However, Band 13 ( $10.25-10.95 \mu\text{m}$ ) is considered here to delineate the coal mine fire zones as transmission of thermal wave is highest in this channel and upwelling (generated by



the additive radiance of atmosphere) appear lowest in this particular thermal channel (Figures 3 and 4).

Thermally emitted radiance from any surface depends on two major factors.

(1) Surface temperature, which is the expression of state of heat energy budget on the surface and also indicate the equilibrium thermodynamic state of incident and emitted thermal energy fluxes.

(2) The surface emissivity, which determines the efficiency of surface for transmitting the radiant energy (Schmugge, 2002).

Therefore band 13 data appear as the best available combination to derive the coal fire map.




Figure 3: Transmission profile in ASTER thermal channel




Figure 4: Upwelling profile in ASTER thermal channel


ASTER data is received as geocoded level 1B format from ERSDAC, Japan. This data is imported in ERDAS 9.1 software after converting in radiance by using facility module available for radiance conversion while importing the data in ERDAS software platform.

The georectified radiance data for 13<sup>th</sup> thermal channel is then used in a model for calculating the radiant temperature from the radiance values using equation - 2.

Table 2: Temperature class of coal mine fire map from ASTER data

| Sl. No. | Temperature Class | Remark                               |
|---------|-------------------|--------------------------------------|
| 1       | < 49° C           | Background temperature               |
| 2       | >49° C - 51° C    | Low intensity coal mine fire         |
| 3       | >51° C - 55° C    | Medium intensity coal mine fire      |
| 4       | > 55° - 60° C     | High intensity active coal mine fire |

### **Methodology Flowchart for preparation of coal mine fire map from ASTER Data**






Figure 6: Colliery wise Coal mine fire map of Jharia coal field, Dhanbad, Jharkhand



## ***CHAPTER V***

### **FIELD WORK**

A fieldwork for ground verification of the fire pixels as observed in the data was carried out in the month of January, 2014. As discussed previously, for the fieldwork a coal fire map as of December 2013 derived from LANDSAT 8 TIRS data (Figure 12, Annexure IV) was used as reference. The observations were then correlated back to the ASTER 2012 data. Metravi© infrared thermometer is used in the field work to measure the temperature of the coal fire. With this thermometer most of the measurements were recorded along the cracks emanating fire/smoke or the heat wave coming out from the fire at subsurface from a typical distance of ~1 m, except for some inaccessible areas. In those cases the measurements were recorded from a distance of ~ 5 m. The device has an accuracy of ~1.5% (in the range of -50°C to 1050°C), and hence is a highly reliable instrument for ground temperature measurement.

Broadly the fire affected area can be differentiated into three categories as follows:

- i. Active fires: where surface expression of the fires are seen in the form of flames.
- ii. Fume cracks: surface cracks emanating fumes arising from the fires below.
- iii. Background: non fire areas in the vicinity comprising of either coal or sandstone.

Most of these fire affected areas are major open cast mines, where the coal has been exposed to the atmosphere and hence is prone to combustion. The locations with the recorded temperature data is tabulated (see Table 4) and shown in the map (marked by numbers in Figure 7). In the south-western flank of the area, fires are located in the region around Bhowra (Location 1) and are mostly fume cracks without the presence of any active fires. The temperature of fumes from these cracks is in the order of 80°C with the associated background temperature of around 60°C. Fire is mostly being dealt by excavating out burning coal in opencast workings. The quarry edges are covered with overburden to suppress the fire expression.

North of Tisra (Location 2), the open cast mines are heavily affected with fires and the same is seen in multiple pockets over a considerably large areal extent. Numbers of fume cracks are seen with temperatures ranging between 116°C to 136°C in reference to background temperatures of 30°C to 67°C. Places near to Bhulanbarari village are also marked by the presence of high intensity coal fires and the fire has created several fissures / fractures over the ground and overburden. Northwest of Tisra, areas around Kujama (Location 3) area also affected by multiple smaller pockets of fire with predominant manifestation of active fires associated with fume cracks. The active fire temperatures are in the order of 250°C and associated fume cracks measure around 90°C. The background sandstones and coal temperatures range between 20°C to 35°C. Similar smaller pockets of fire are seen in areas around Ghanoodih (Location 4). Here active fire temperatures range between 200°C to 400°C against a background of 35°C. Further on the north eastern flank, two smaller fire pockets are located in the areas near Bastacolla (Location 5) and South Jharia OCP (Location 6). Large scale excavations are ongoing to isolate the fire affected seams and control the spread of the fire. These areas are mostly manifested by fume cracks with temperatures around 70 °C to 80 °C against a background of 40°C to 60°C. Very occasionally surface active fires are seen with higher temperatures.

Active fires in the area have temperatures of around 260°C with associated fume cracks measuring 70°C against a background of 35°C. The open cast mines in Kusunda and Kenduadih are known to be the "exhibits" of active fire of the Jharia coalfield. The surface manifestations of these fires are in the form of blazing flames (Figure 12) with very high temperatures. The extent of the area affected is large. Fumes for the burning coal are also associated with the sulphur. Spontaneous burning of coal creates huge amount of obnoxious gases like sulphur dioxide and hydrogen sulphide etc.

Towards the northwest, Near Bansjora (Location 11) railway station a fire zone is seen in an excavation pit. This pit is constructed to thwart the progress of coal fire and hence the present manifestation of the fire is greatly diminished. Similarly, areas around Modidih, Jogta and Katras are affected by multiple fire pockets mainly associated with the ongoing mining in these areas. The expressions are mainly in the form of fume cracks with few active fires. The fume cracks have temperatures around 60°C to 70°C against an average background temperature 32°C. Though the fire

pockets are isolated from each other on the surface, they culminatively affect a large area around Katras, Modidih, Gaslitand and Jogta (Location 12 to 20).

In the western flank, mines in the Nadhkhurki (Block 2 OCP, Location 22) are highly affected by fire. The accessible mining area has been greatly reduced due to the presence of multiple fume cracks rendering the area highly unstable. The measured fume crack temperatures range between 90°C to 110°C against an average background of 40°C. North of Nadhkhurki, minor fire pockets are seen around the Jayramdih (Bendih, Location 21). The fire is mostly related to the overburden dumps in the region.

The fire zones in the Shatabdih (Location 24) and the Muraidih (Location 23) mines are continuously being excavated to isolate the affected coal seams. These efforts have resulted in overall decrease in the spatial extent of the fire and thereby its manifestation in the satellite data. However, multiple smaller pockets remain, mostly that of fume cracks with temperatures ranging from 85°C to 90°C against a background of around 35°C to 40°C. Further, in areas around New Akash Kinari (Location 25 and 26) situated near DC railway line, the fires have been blanketed with soil.

The fieldwork ascertained the major fire pockets as seen in from the data (figure 5). However, the observations also indicate the following:

The thresholding method as discussed in section 4.2.1 has masked a prominent fire location in the Bhulanbarari area (marked with "red star" in figure 7). Here, though active fire locations are seen on the surface, the same is not manifested in the data.

Considering the above mentioned observations, certain post field update is necessitated.



## ***CHAPTER VII***

### **DISCUSSIONS AND CONCLUSIONS**

In summary, there is a change in the areal disposition of the fires from 2006 to 2012. Observations suggest the diminishing of the fire affected areas in the eastern and western flank but emergence of new areas in the northern sections in areas around Katras and Gaslitand. Concurrently, there is a decrease in extent of fire areas around Lodna, Tisra area in the eastern flank and Shatabdi, Nadkhurkee area in the western flank from 2006 to 2012. A quantitative comparison of the 2006 and 2012 data was carried out. As discussed previously, the inclusion of fires from the Bhulanbarai area was not detected by regional-iterative thresholding but was separately identified using "cluster analysis" method. Therefore, comparison of the 2006 fire area with 2012 was done including the fires from the Bhulanbarari colliery (considering them as a part of the active fire) derived independently for this area.

As compared 2006, when the total fire affected extent of about 3.01 km<sup>2</sup>; in 2012 total fire affected extent is about 2.18 km<sup>2</sup>. The colliery wise break-up of change in fire area from 2006 to 2012 is given in Annexure V.

### **Conclusions**

The following conclusions can be made:

1. As of the date of study in the year 2012 and in comparison with the previous study done in 2006, there has been a change in areal extent and disposition of the fire affected areas.
2. Compared to 2006, the eastern flanks (Lodna, Tisra areas) and the western flank (Nadkhurkee, Shatabdi, Block II and Benedih area) show diminished fire presence.
3. New fire areas are observed in the northern flank in the areas around Katras, Gaslitand etc. These areas were not mapped as fire in the 2006 study.
4. The mines in Kusunda, Kenduadih and Ena remain to be the worst affected with maximum presence of active fires. This observation remains consistent to the findings as in 2006.

5. There is a decrease in areal extent of the fire (Figure 10) from 2006 to 2012.

**Note:** Estimations of fire extent (in terms of sq.km.) both in 2006 and in the present 2012 study are pixel based. They do not represent the actual ground area under fire. These estimations are made for comparative purpose only, to indicate the increase or decrease of areal disposition of fire. Hence, they should not be quoted as fire area on the ground.




Figure 10: Total fire area statistics

*Annexure –I*

Table 3: Sensor details of ASTER data

| Subsystem | Band No. | Spectral Range<br>( $\mu\text{m}$ ) | Spatial<br>Resolution<br>(m) | Quantization<br>Levels |
|-----------|----------|-------------------------------------|------------------------------|------------------------|
| VNIR      | 1        | 0.52-0.60                           | 15                           | 8 bits                 |
|           | 2        | 0.63-0.69                           |                              |                        |
|           | 3N       | 0.78-0.86                           |                              |                        |
| SWIR      | 4        | 1.60-1.70                           | 30                           | 8 bits                 |
|           | 5        | 2.145-2.185                         |                              |                        |
|           | 6        | 2.185-2.225                         |                              |                        |
|           | 7        | 2.235-2.285                         |                              |                        |
|           | 8        | 2.295-2.365                         |                              |                        |
|           | 9        | 2.360-2.430                         |                              |                        |
| TIR       | 10       | 8.125-8.475                         | 90                           | 12 bits                |
|           | 11       | 8.475-8.825                         |                              |                        |
|           | 12       | 8.925-9.275                         |                              |                        |
|           | 13       | 10.25-10.95                         |                              |                        |
|           | 14       | 10.95-11.65                         |                              |                        |

*Annexure –II*

Table – 4: Ground Temperature measured during fieldwork

| No. | Location Name (ASTER)                    | Location Coordinates          | Seen in L8 TIRS 2013 data (Y/N) | Feature                            | Approximate Size   | Temperature                                | Background temperature                      |
|-----|--|-------------------------------|---------------------------------|------------------------------------|--|--|---|
| 1   | Bhaunra                                  | 86°23'21.694"E 23°41'18.314"N | Y                               | Opencast mine and related OB dumps | 800m by 500 m  | 80   | 62  |
| 2   | East of Basra (North Tisra)              | 86°26'19.605"E 23°43'47.937"N | Y                               | Open cast mining                   | Multiple fire pockets, Large area affected                   | varies from 116 to 136                     | varies from 30 to 67                        |
| 3   | Kujama                                   | 86°25'36.418"E 23°44'9.206"N  | Y                               | Open cast mining                   | Large area affected  | Active fire: 260<br>Smoky coal: 90         | 5st: 20<br>Coal: 35                         |
| 4   | East of Jharia (Dhanudih)                | 86°25'33.867"E 23°44'30.028"N | N                               | Open cast mining                   | moderate area affected. Excavations on going to remove fire. | Fume cracks: 79<br>Active fire: 180 to 440 | average background : 35                     |
| 5   | Bastakola                                | 86°24'54.284"E 23°45'26.751"N |                                 | Open cast mining                   | moderate area affected                                       | Fume cracks: 76<br>Active fire: 560        | average background : 37 to 56               |
| 6   | South Jharia OCP                         | 86°25'8.432"E 23°45'7.39"N    |                                 | Open cast mining                   | moderate area affected                                       | Fume cracks: 160                           | 56  |
| 7   | Ena OCP                                  | 86°23'57.187"E 23°45'26.267"N | Y                               | Open cast mining                   | Large area affected  | Fume cracks: 70<br>Active fires: 263       | varies from 23 to 32                        |
| 8   |  | 86°23'41.772"E 23°46'1.53"N   | Y                               |                                    |  |  |   |
| 9   |  | 86°23'57.006"E 23°46'5.665"N  | Y                               |                                    |  |  | Active fire. Temperatures greater than 1000 |
| 10  | Kusunda - Kendudhi OCP                   | 86°23'20.94"E 23°46'37.223"N  | Y                               | Open cast mining                   | Large area affected  | Large area of active fires                 |   |
| 11  | NE of Loyabad (Bansjora Railway Station) | 86°21'45.788"E 23°47'14.425"N | N                               | Old OCP abandoned                  | moderate   | Fume cracks: 60                            | 32  |
| 12  | Katras OCP                               | 86°20'31.487"E 23°47'12.755"N | Y                               | Ob dump fire                       | moderate   | Active fire: 280 to 500                    | 53  |
| 13  | Katras OCP (Modidih/Jogta Sector)        | 86°19'56.592"E 23°47'4.001"N  | Y                               | Open cast mining                   | Large area affected  | not accessible                             | varies from 35 to 42                        |
| 14  | N of shyambazar (AWMC outsourced)        | 86°20'15.618"E 23°47'36.688"N | Y                               | Open cast mining                   | small area affected  | Fume cracks: 72                            | varies from 30 to 40                        |
| 15  | Modidih (Sijuah)                         | 86°20'15.908"E 23°47'35.058"N |                                 | Open cast mining                   | small area affected  | Fume cracks: 1120                          | varies from 30 to 41                        |
| 16  | Katras                                   | 86°18'46.53"E 23°47'39.016"N  | Y                               | OB dump associated to OCP          | moderate area affected                                       | not accessible                             | not accessible                              |
| 17  | Katras                                   | 86°19'13.206"E 23°47'19.661"N | Y                               | Open cast mining                   | Large area affected  | fume cracks: 60-70<br>Active fire: 559     | varies from 29 to 40                        |
| 18  | Katras                                   | 86°19'2.992"E 23°46'56.521"N  | Y                               |                                    |  |  |   |
| 19  | Katras                                   | 86°19'4.247"E 23°46'58.769"N  | Y                               |                                    |  |  |   |
| 20  | W of Shyambazar (From L8)                | 86°18'55.812"E 23°47'11.417"N | ---                             | Large OCP ongoing                  | Large area affected  | not accessible                             | varies from 22 to 30                        |
| 21  | Jayaramdih (Bendih)                      | 86°12'35.373"E 23°46'52.837"N | N                               | OB dump                            | moderate   | fume cracks: 85                            | varies from 35 to 40                        |
| 22  | Nadkharki : Block 2 OCP                  | 86°12'28.599"E 23°46'33.323"N | Y                               | Open cast mining                   | Large area affected  | fume cracks: 110-90                        | varies from 35 to 43                        |
| 23  | Murardih OCP                             | 86°14'2.223"E 23°47'41.296"N  | N                               | Open cast mining                   | moderate area affected                                       | fume cracks: 85 - 90                       | varies 35 to 40                             |
| 24  | Shatabdi OCP                             | 86°14'13.223"E 23°47'12.357"N | N                               | Open cast mining                   | moderate area affected                                       | not accessible                             | varies 35 to 40                             |
| 25  | Govindpur area: New Akash                | 86°17'0.438"E 23°47'43.058"N  | N                               | underground                        |  |  |   |
| 26  | kinari colliery                          | 86°17'6.953"E 23°47'22.249"N  | N                               | mining activity                    | Moderate Area affected                                       | fume cracks : 67 to 70                     | varies from 31 to 35                        |



*Annexure –V*

Table 6: Colliery wise break-up of change in fire area from 2006 to 2012

| SL. NO. | COLLIERY AREA NAME   | FIRE AREA 2006 (SQ. KM.) | FIRE AREA 2012 (SQ. KM.) | AREA CHANGE (SQ. KM.) | INCREASE/ DECREASE |
|---------|----------------------|--------------------------|--------------------------|-----------------------|--------------------|
| 1       | DAMODA               | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 2       | TISCO (west)         | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 3       | IISCO                | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 4       | TISCO (north)        | 0.0000                   | 0.0885                   | 0.089                 | INCREASE           |
| 5       | NUDKHURKEE OCP       | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 6       | BENEDIH OCP          | 0.0050                   | 0.0530                   | 0.048                 | INCREASE           |
| 7       | BLOCK-II OCP         | 0.0891                   | 0.0530                   | -0.036                | DECREASE           |
| 8       | MURAIH OCP           | 0.0425                   | 0.1478                   | 0.105                 | INCREASE           |
| 9       | SHATABDI OCP         | 0.2005                   | 0.0378                   | -0.163                | DECREASE           |
| 10      | TETURIA              | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 11      | S.GOVINDPUR          | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 12      | KORIDIH BLOCK-IV OCP | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 13      | JOGLIDH              | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 14      | DHARAMABAND          | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 15      | MAHESHPUR            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 16      | PHULARITAND          | 0.0030                   | 0.0133                   | 0.010                 | INCREASE           |
| 17      | MADHUBAND            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 18      | AKASH KINARI         | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 19      | GOVINDPUR            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 20      | E. KATRAS            | 0.0000                   | 0.0133                   | 0.013                 | INCREASE           |
| 21      | KATRAS-CHOITUDIH     | 0.0000                   | 0.1021                   | 0.102                 | INCREASE           |
| 22      | KESHALPUR            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 23      | RAMKANALI            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 24      | NICHITPUR            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 25      | E. BASURIA           | 0.0162                   | 0.0000                   | -0.016                | DECREASE           |
| 26      | KHAS KUSUNDA         | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 27      | GONDUDIH             | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 28      | W. GODHAR            | 0.0000                   | 0.0012                   | 0.001                 | INCREASE           |
| 29      | BASURIA              | 0.0003                   | 0.0000                   | -0.0003               | DECREASE           |
| 30      | TETULMARI            | 0.0041                   | 0.0223                   | 0.018                 | INCREASE           |
| 31      | DHANSAR              | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 32      | GODHAR               | 0.0017                   | 0.1073                   | 0.106                 | INCREASE           |
| 33      | INDUSTRY             | 0.0193                   | 0.0119                   | -0.007                | DECREASE           |
| 34      | KUSUNDA              | 0.7816                   | 0.4243                   | -0.357                | DECREASE           |
| 35      | SENDRA-BANSJORA      | 0.1221                   | 0.0796                   | -0.043                | DECREASE           |
| 36      | BASTACOLLA           | 0.0384                   | 0.0663                   | 0.028                 | INCREASE           |
| 37      | BERA                 | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 38      | KUYA                 | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 39      | GOLUCKDIH            | 0.3109                   | 0.0301                   | -0.281                | DECREASE           |

| SL. NO. | COLLIERY AREA NAME  | FIRE AREA 2006 (SQ. KM.) | FIRE AREA 2012 (SQ. KM.) | AREA CHANGE (SQ. KM.) | INCREASE/ DECREASE |
|---------|---------------------|--------------------------|--------------------------|-----------------------|--------------------|
| 40      | KUJAMA              | 0.0988                   | 0.0398                   | -0.059                | DECREASE           |
| 41      | S. JHARIA-R. OCP    | 0.1284                   | 0.0244                   | -0.104                | DECREASE           |
| 42      | DOBARI              | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 43      | GONHOODIH           | 0.0844                   | 0.0398                   | -0.045                | DECREASE           |
| 44      | SIMLABAHAL          | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 45      | HURRILADIH&STD      | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 46      | ENA                 | 0.1972                   | 0.0918                   | -0.105                | DECREASE           |
| 47      | BURRAGARH           | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 48      | N. TISRA            | 0.1244                   | 0.0098                   | -0.115                | DECREASE           |
| 49      | LODNA               | 0.1689                   | 0.0000                   | -0.169                | DECREASE           |
| 50      | S. TISRA            | 0.0153                   | 0.0000                   | -0.015                | DECREASE           |
| 51      | BARAREE             | 0.1578                   | 0.1037                   | -0.054                | DECREASE           |
| 52      | AMLABAD             | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 53      | PATHERDIH           | 0.0020                   | 0.0000                   | -0.002                | DECREASE           |
| 54      | SUDAMDIH            | 0.0547                   | 0.0000                   | -0.055                | DECREASE           |
| 55      | SITANALA            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 56      | MURULIDIH 20/21 PIT | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 57      | MURULIDIH           | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 58      | BHATDIH             | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 59      | LOHAPATTY           | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 60      | IISCO               | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 61      | TASRA-IISCO         | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 62      | KENDUADIH           | 0.0000                   | 0.0610                   | 0.061                 | INCREASE           |
| 63      | BULLIHARY           | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 64      | GOPALICHUCK         | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 65      | POOTKEE             | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 66      | BHURUNGIA           | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 67      | KHARKHAREE          | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 68      | GASLITANO           | 0.0000                   | 0.1194                   | 0.119                 | INCREASE           |
| 69      | KANKANEE            | 0.0000                   | 0.0530                   | 0.053                 | INCREASE           |
| 70      | MUDIDIH             | 0.0000                   | 0.1141                   | 0.114                 | INCREASE           |
| 71      | W. MUDIDIH          | 0.1125                   | 0.0171                   | -0.095                | DECREASE           |
| 72      | LOYABAD             | 0.0000                   | 0.0133                   | 0.013                 | INCREASE           |
| 73      | BHAGABAND           | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 74      | MOONIDIH PROJECT    | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 75      | E.BHUGGATDIH        | 0.0194                   | 0.0022                   | -0.017                | DECREASE           |
| 76      | ALKUSHA             | 0.0000                   | 0.0326                   | 0.033                 | INCREASE           |
| 77      | KUSTORE             | 0.0289                   | 0.0524                   | 0.024                 | INCREASE           |
| 78      | ANGARAPATRA         | 0.0292                   | 0.1331                   | 0.104                 | INCREASE           |
| 79      | SALANPUR            | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 80      | BHOWRAH. N          | 0.0081                   | 0.0133                   | 0.005                 | INCREASE           |

| SL. NO. | COLLIERY AREA NAME | FIRE AREA 2006 (SQ. KM.) | FIRE AREA 2012 (SQ. KM.) | AREA CHANGE (SQ. KM.) | INCREASE/ DECREASE |
|---------|--------------------|--------------------------|--------------------------|-----------------------|--------------------|
| 81      | BHOWRAH. S         | 0.0162                   | 0.0000                   | -0.016                | DECREASE           |
| 82      | BAGDIGI            | 0.0373                   | 0.0000                   | -0.037                | DECREASE           |
| 83      | JEALGORA           | 0.0227                   | 0.0000                   | -0.023                | DECREASE           |
| 84      | JEENAGORA          | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 85      | JOYRAMPUR          | 0.0567                   | 0.0099                   | -0.047                | DECREASE           |
| 86      | CHANDAN OCP        | 0.0000                   | 0.0000                   | 0.000                 | NO FIRE            |
| 87      | BANSDEOPUR         | 0.0072                   | 0.0000                   | -0.007                | DECREASE           |
|         | <b>TOTAL AREA</b>  | <b>3.01</b>              | <b>2.18</b>              | <b>-0.823</b>         | <b>DECREASE</b>    |

**Note:**

- 1) "NO FIRE" implicates that the fire has not been identified satellite data (*either absent or below sensor resolution*)
- 2) "**INCREASE**" implies, increase in fire area OR emergence of fire areas not identified in 2006 study
- 3) "**DECREASE**" implies, decrease in fire area OR fire areas in 2006 not identified in present study (*either absent or below sensor resolution*)
- 4) Estimations of fire extent (in terms of sq.km.) both in 2006 and in the present 2012 study are pixel based. They do not represent the actual ground area under fire. These estimations are made for comparative purpose only, to indicate the increase or decrease of areal disposition of fire. Hence, they should not be quoted as fire area on the ground.



Figure 14: Active fire exposed in Kusunda/Kenduadih area



Figure 15: Excavations to isolate fire affected seams Ena area